MAR 1 6 1998

SECTION	LAND	LAND CORNER RECORDATION CERTIFICATE			FILED		
For corners in	Filing	Requirement of Ac	et 74, Mich. P.A. 1970	AT 2.35	O'CLOCK1		
MAS ON County)	Located In:	Corner	Code ≠#	NO	V 2 2 1994		
Public Land Survey	T 19N R T R T R T R			MA MA	GOLDEN KOLASKI SON COUNTY STER OF DEEDS		
 Property Controlling in Section Miscellaneous Property in Pec. 	S T R S T R S T R S T R		Re		amp & File Number		
4. Lot No, Re 5. Private Claims				ABCDE	FGHIJKLM		
				2 6 5	-4-1-3-1-2-1-1		
Theodore B. Weinert do hereby certify that under requ in lines 1 and 2 above were in a current manual of survey instruct Management or by a decree of a c above were in conformance with Court of Law; established, re- expressed below:	irements of P.A. 74, Miclonformance with regul tions of the United Stat Court of Law and/or that the rules of the Michiga established, monumer	nigan P.A. of 1970, the contains and rules therefores Department of the Intitle Corner points mention Board of Land Surveyonted, re-monumented, in	rner points mentioned ore as required in the terior, Bureau of Land ened in tines 3, 4 and 5 ors or by a Decree of a recovered, found as	4 7 8 5 6 18 17 7 8 19 20 9 10 30 29	-9 10 11 12 15 14 13 14 13 14 13 14 13 14 13 14 15 14 13 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 13 14 15 16 15 16 15 16 15 16 15 16 15 16 15 16 16 15 16		
NOTE: Not more than 4 cor on this certificate.	mers, all in the same	town and range, may	y be recorded	12 31 32	33 34 35 36		
A. Description of original materials of the L-7 1/4 Corner, Secs. 1 G.L.O. Notes Set Que July 7, 1838, Sylves 8" Beech N 25 N 20 1 8" Beech S 10 N 10 1 August 27-29, 1888, post on a split distance.	3 & 24 orter Section Post ster Sibley ks ks J. A. Mitchell pl	anted iron	Undated record from stake Iron stake South 33 none of these witnes October 3, 1986, Samonument box witnes December 17, 1981, monument box no wit	orth 33.00' 8.00' Pence Post esses remain m Barnett, PLS, es given one of w Ken Ross, PLS, P	South 30.16' Fd iron pin in . hich remains .		
B. Description of corner evidence L-7 1/4 Corner, Secs. 1 Found 1" Axle Shaft Attempted to remove left in place. Fit distances Bast a surveys by Sam Barne Fit distances east a recorded by J. A. Mi This corner location faithful perpetuatio	3 & 24 in monument box this iron with no nd West as describ tt, PLS, & Ken Ros nd west within 7.0 tchell is accepted as a	success, ed in the s, PLS. feet as careful and	toring or reestablishing	corner:			
C. Description of monument	for corner and acces	ssories established to	perpetuate locating the	position of the co	rner:		
L-7 1/4 Corner, Secs. 1. 1" Axle Shaft in mon Spike in Power Pole I CL Steel I-Beam Post NE Corner Wood Porch CL 18" Maple S 53 W 4 On CL Millerton Road	ment box. N 20 E 32.40' S 14 E 24.80' S 25 W 68.58'		The state of	AND	Poor Group Reviewed and Livinowed and Livinowed Committee of the March Council		
Signed by Churin	Hy Jua	//-	Date _///	194	ŭ l ·		
Surveyor's Michigan License f		Peer Group Reviewed and Approved	FORM APPROV	ED BY MICHIGAN STATE BOARD	OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975		
LIBER 3PAGE	233	Kenneth L. Ross Mason County Surveyor	The Land		REVISED JAN. 1983		