## SUFFVEY & REMONUMENTATION

OCT 2 9 1996

COMMISSIO	N LAND CORN	LAND CORNER RECORDATION CERTIFICATE			
COMME	Filing Requ	irement of Act 74, Mich. P.A.	1970 FILED		
For comers in			AT 9:17 O'CLOCK a M		
Mason County (County)	Located In:	Corner Code #	W W		
Public Land Survey	T 19N R 17W T R T R	F-11	OCT   5 996		
Property Controlling     in Section     Alignatism and a	T R S T R S T R		REGISTER OF DEEDS		
Miscellaneous     Property in Sec.	STR STR		Register of Deeds Stamp & File Number		
	Recorded Plat		,ABCDEFGHIJKL		
5. Private Claims					
			2 6 6 4 8 2 1		
I, Theodore H. Wei	nert , in a field surve	yon September 21,1996 ,	4 7 8 9 10 10 11 19		
do hereby certify that under in lines 1 and 2 above we	requirements of P.A. 74, Michigan P re in conformance with regulations a structions of the United States Depar	A. of 1970, the corner points mention	ed 5		
Management or by a decree above were in conformance	of a Court of Law and/or that the co with the rules of the Michigan Board	rner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of	15 7		
Court of Law; established expressed below:	ed, re-established, monumented, a	re-monumented, recovered, found	8 19 20 21 22 23 24 9		
NOTE: Not more than on this certific	4 corners, all in the same towr	n and range, may be recorded	10 30 29 28 27 26 25		
	al monument and accessories an		12 31 32 33 34 35 36		
Witnesses given (3) 1 found during research  B. Description of come on September 21, 1996 existing iron and pul	point of intersection of 4 8" Maple, N23°E, 18.35', (4) of this corner. If evidence found and/or method a 7, I found the 5/8" X 18" Re- led. I searched for additional eases (1) and (2) have been	way fence, corresponding to 9" Pine, N77-E, 50.17', (5) applied in restoring or reestablishing rod and cap # 18223 as described and	te 267, Mason County Records. Stated a survey by John S. Mitchell, May, 1892". 30" Maple, S30°E, 86.27'. No other data ong corner:  ibed in "A" above. I cross pinned the other evidence to dispute the location 4) and (5) are standing and in good		
I replaced the 5/8" X accepted as a careful (4) Sp. (5) Sp. Spike: Spike: 1 4" P. Center	ment for corner and accessories  18" re-rod and cap, with a and faithful reestablishmen ike in 12" Red Pine, N 85°E, ike in 36" Triple Maple, S26 in 8" Spruce, S50°W, 27.23' in 8" Jack Pine, N32°W, 24.3i ipe 6' long, Due North, 1.25 -line of two track road, S45 of fence North, South, East	Standard Mason County Monume t of the position of the ori 50.31' •E, 85.81' •W, 14.00'	nt, place flush with the ground, and is ginal corner. Witnesses Taken:		
Surveyor's Michigan Lices	nse No. 19846		APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971		
		Peer Group Reviewed and Approved Date:  Kenneth L. Ross Mason County Surveyor	REVISED MAY 14, 197; REVISED JAM., 1933 ADAPTED FOR WORD PROCESSING MARCH, 1993		

ADACE OF