MAR 1 6 1998 AND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

SECTION		-		FILED	
FOR CORNERS OF -: L	OCÂTED IN-:	CORNER CODE	NUMBER AT	10:10 octoo	<u> </u>
1. PUBLIC LAND SURVEY T	20N N. 15W E. S., R. W.	F3		NOV 17	1004
2. PROPERTY CONTROLL. ING IN SECTION,T.	N. E. W. W.	Seg. 2		MARY GOLDEN	
3. MISCELLANEOUS PROPERTY IN SECTION, T.	•	<i></i>		MASON CO REGISTER OF	UNTY
4. LOT NO, RECORDS	D PLAT		·		
5. PRIVATE CLAIMS	· · · · · · · · · · · · · · · · · · ·		·		
				REGISTER OF DEEDS FILING NUM	
I,	do hereby certify	that under requi	rements of P	P.A.74, Michigan P	.A. of 1970,
19 , four	conformance with regular conformance with regular defends of the corner points mend, recovered, restored, estates.	, re-established, lations and rules the Interior, Bure entioned in lines stablished or re-e	monumented therefore as au of Land M 3,4 and 5 a established a	a, re-monumented, required in the cu Management or by a bove were, in a fie as expressed below	recovered or rrent manual decree of a ld survey on and in con-
formance with the rules of the Miclaw:	nigan State Board of Re	egistration for La	ind Surveyor	s or, by a Decree o	of a Court of
1/4 corner common to sect 1839 survey by John Brink Set Wood Post #1 P.Pine 8 S78-30W 110 links #2 P.Pine 3 N20E 311links 1918 search by C.E.Mitchell Set concrete monument #3 Oak 5 S19W 97 links #4 Pine 10 S79E 29 links	tions 4 and 9 of T20N F 1984 survey by R. Hays#2584 Fd. Concrete Monument No witnesses mentioned Undated survey by Ken Ro No monument mentioned #5 SW 4 West 2544.34 feet #6 SE 4 East 2545.45 feet	.7 1986 survey S m it ess #17634 m # # #	onument by Mit	I fd. the concrete tchell. Replaced y 60" long conc. ass cap. N 36.48 feet DW 61.11feet E 3.86 feet 1E 12.52 feet	W.
B. Description of corner evidence	found and/or method app	lied in restoring	or re-establi	ishing corner:	E W
condition. My distances eas gone. I found the remains of condition. I could find no co- monument is accepted as the There is a cabin S12W 264 to	t and west check Ross's f both Mitchell witnesses officting information that be best available evidence	within .10 feet. Witness 7 thro would lead to an	Witnesses 1 ugh 11 are i other locatio	and 2 are n good on. This	Peer Group Review
					8
C. Description of monument for co	orner and accessories es	stablished to perp	etuate, locat	ting the position of	the comer:
1/4 corner common to sect Monu. The 5" square by 60" Witnesses: Iron fence post West 2.01 fe B.Oak 9 N67W 36.48 feet (# B.Oak 11 N22W 61.09 feet (J.Pine 9 N66E 3.86 feet (#9) W.Oak 6 S53E 12.52 feet (# B.Oak 10 S53W 32.75 feet (#	long concrete monu. wit et 7) #8)		PATR:	CK K. MON	Mason County Surveyor
SIGNED BY Value (.	Sum	DA	TE	CONTRACTOR OF THE PARTY OF THE	
SURVEYOR'S MICHIGAN REGISTI	RATION NO.		Octob	er 30, 1994 (seal.)	
FOR STATE AND UNITED STATE	315	95	1,11,11,111	-	
MANES BY	HEF OF SURVEY PARTY	DA	TE		
APPROVED AND SIGNED BY			DATE		
	MICHIGAN REGISTERED LAN	D SURVEYOR		(SEAL)	
	17	RER 3	PAGE 20	DK -	