MAR 1 6 1998LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 SECTION FILED CORNER CODE NUMBER FOR CORNERS OF -: LOCATED IN -: 20N N. 1. PUBLIC LAND SURVEY... nov | 7 <u>190</u>1 2. PROPERTY CONTROLL-ING IN SECTION-(GOLDEN KOLASKI KASON COUNTY 3. MISCELLANEOUS _ ,T._ PROPERTY IN SECTION. REGISTER OF DEEDS ____ , RECORDED PLAT_ 5. PRIVATE CLAIMS_ REGISTER OF DEEDS STAMP AND FILING NUMBER Patrick R. Leemon do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a _____19___, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Section corner common to sections 4, 5, 8 and 9 of 120N R15W 1639 survey by John Brink 1918 survey by C.E. Mitchell Co. Sur. 1971 survey by Robert A. Griffin #13584 Set Wood Post #1 P.Pine 4 S53E 4 links Searched for and found the concrete **Set Concrete Monument** #3 W.Oak 15 N27W 194 links monument by Mitchelf. Replaced it #2 P.Pine 4 N83W 7 links #4 R,Oak 8 S75E 146 links w/ a 5" sq. by 60" long conc. monument w/ 3" brass cap. #8 W.Oak 9 N65E 74.31 feet 1974 survey by C.Cole #17615 1938 Search by Ray Lyons USFS Used witnesses #8, 5 and 11 #5 B.Oak 18 S81E 12.38 feet Fd. concrete monument #5 B.Oak 12 S81E .18 chains #9 Tw.W.Oak 7x8 S46E 86,53 feet #10 W.Oak 8 West 105,03 feet #6 W.Oak 18 S23W 1.46 chains #11 B.Oak 5 N73W 73.86 feet #7 B.Oak 8 N82VV 1.28 chains B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Lifound the 5" square by 60" long concrete monument w/ brass cap by Griffin 158 feet North of the centerline of the E-W trail road, off the centerline of the road to the North and 11 feet east of centerline of the curve. Witnesses 1 through 4 and 7 are gone. Witness 9 is not longer a twin as one tree fell over. Witnesses 5, 8, 10 and 11 are in good condition. Liber 1 Page 42 by Griffin documents the history of this corner. I could find no conflicting information that would lead to another location. This monument is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner section corner common to sections 4, 5, 8 and 9 of T20N R15W OF MICH, Monu. The 5" square by 60" long concrete monu. with 3" brass disk was left in place. Witnesses:

Iron fence post North 1 45 feet PATRICK R Iron fence post North 1.45 feet LEEMON W.Oak 11 S68E 64.40 feet LAND W.Oak 11 S46E 87.02 feet (#9) SURVETOR W.Oak 12 N68E 74.32 feet (#8) No. B.Oak 22 S85E 12.15 feet (#5) 31595 W.Oak 9 S86W 105.05 feet (#10) OLAND B.Oak 8 N73W 73.84 feet (#11) SIGNED BY... _ DATE _ 31595 SURVEYOR'S MICHIGAN REGISTRATION NO. FOR STATE AND UNITED STATES AGENCIES: SIGNED BY. _ DATE. CHIEF OF SURVEY PARTY APPROVED AND SIGNED BY. _ DATE_ MICHIGAN REGISTERED LAND SURVEYOR

D. _____

LIBER

3 PAGE 204

Form No. MLM735 DOUBLEDAY BROS. & CO., KALAMAZDO, MICH.