SURVEY & REMONUMENTATION

MAR 1 6 1998

LAND CORNER RECORDATION CERTIFICATE

CECTION	Filing Require	Filing Requirement of Act 74, Mich. P.A. 19					, FILED						
SECTION For corners in			,	ıı.	1,2				_				
Mason Lo	cated In:	Corner Code #	AT	<u> 4</u>	04	<u> 0'CLC</u>	<u>)CK</u>	=7-{	>	1			
(oodily)					١			1		ļ			
Public Land Survey T_	20N R 16W	C-13			N	DV 20) 1997						
	R		- 1 1										
T_	<u> </u>			1			n Kola	SKI		1			
							COUNTY OF DEEL	10		ĺ			
	R R									į			
in Section S T 3. Miscellaneous S T R	N		Re	giste	r of De	eas St	amp & F	tie N	umbe	Γ			
Property in Sec. ST_	R												
4. Lot No, Recorded Plat				1 A	8 0	DE	FG	H 1	J K	Ł			
5. Private Claims				2	6	5	4	3	2	i			
				3			7	Ĭ					
L Richard L. Hays	in a field eveney on	August	10 07	4	7	8	9	10	11	12			
do hereby certify that under requirements	of P.A. 74. Michigan P.A	. of 1970, the corner	points mentioned	5									
in lines 1 and 2 above were in conformation	ance with regulations ar	nd rules therefore a	as required in the	6	18	17	16	15	14	13			
current manual of survey instructions of the Management or by a decree of a Court of L	aw and/or that the com-	er points mentioned	in lines 3, 4 and 5	7									
above were in conformance with the rules	of the Michigan Board	of Land Surveyors o	or by a Decree of a	8	19	S D	21	22	23	24			
Court of Law; established, re-esstable expressed below:	isnea, monumentea, re	e-monumentea, rec	overed, found as	Ŷ			•						
•				10	30	29	28	27	26	25			
NOTE: Not more than 4 corners, all on this certificate.	I in the same town an	id range, may be	recorded	11	·								
				12	31	32	33	34	35	36			
A. Description of original monument	and accessories and/	or subsequent res	toration:	13 1									
C-13 SOUTHEAST CORNER OF SE 1839: G.L.O Survey		Lawrance Slate	er Survey #7439										
12" Beech N-64°-E 47 1	• • • • • • • • • • • • • • • • • • • •	t.C. LIBER 2, Po	175										
8" Beech N-35°-W 31 1		l 1/2" Re-Rod of Telephone Ris	er N-45°-E 54	.00'	(4)								
1891: J.W. Griswold Survey	-	Sign Post	S-50°-E 6 S-05°-W 29	3.45	(5)								
Deputy County Surveyor No Witnesses			S-20*-W 27										
1981:Ross Survey R.L.S. #1 SW Corner to South Quarter													
Section 32 2622.30' (
			*										
B. Description of corner evidence for	und and/or method ap	plied in restoring o	or reestablishing co	mer:									
C-13 SOUTHEAST CORNER OF SE August 1997: Found 1/2" Re-R	od. Condition of t	: :he Witnesses ar	e as follows:										
12"	Beech N-64°-E	47 1ks	(1) (GONE) (2) (GONE)										
SW Corner to South Quarter		2622.30'											
Top of Telephone R			(4) (GONE) (5) (FOUND)										
Stop Sign Post Power Pole	S-05°-W		(6) (GONE)										
Face Stop Sign Pos	t S-20°-W	27.45'	(7) (GONE)										
·													
		-											
C. Description of monument for corr	ner and accessories es	tablished to perpe	tuate locating the	positi	on of th	ne com	er:						
C-13 SOUTHEAST CORNER OF SE August 1997: Replace the 1/	2" Re-Rod with the	standard Mason	County Monument	. 88 8	care	ful an	đ faith	fv1					
re-establishment of the pos	ition of the Origin	al Corner.		•									
1/2" Re- 1/2" Re-		3.65' ₃											
1/2" Re-	Rod S-80°-W 2	9.10' ' 6.50'				•			:, 3,				
Spike in NE Side of Power P South Edge of Stop Sign 1/2" Re-		4.45'				t	•						
5/8" Re-		9.04'		:		:	•		4.				
						, ",							
	6		. /		. ,	۳. ,							
(1-) 1 ×	1 1 1	D-1-	11/6/9	17		•							
Signed by // lehael	tage	·Date				·							
Surveyor's Michigan License No259	847	CHATTER E Williams	FORM APPR	OVED BY	HICHIGA	ISTATE 00	ARD OF LAND		EVISED MA	Y 14, 1			
	Date: 1	and App. 2, 189	Z62			ADAPTI	ED FOR WORL		REVISED	JAN., 1			
LIBER 4 PAGE	185	2 /	The same of the sa										
CIDCH	/	Venue wa											