MAR 1 6 1998

expressed below:

4									
and the second of the second	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 FILED								
SECTION									
For corners in MASON (County)	Located In:	Corner Code #	7 2:5				- 	2 M	
Public Land Survey	T 20N R 16W T R T R	<u>r-13</u>	M/s	iil LU	100 DEG	KUĽAS	iki		
Property Controlling in Section Miscellaneous	T R S T R S T R R S T R		MASON COUNTY REGISTER OF DEEDS Register of Deeds Stamp & File Number						
Property in Sec.	STR	**************************************							
4. Lot No, 1 5. Private Claims	Recorded Plat		·	A 8	C D	E F (3 H	l J K	L
			2	6	5	4	3	2	3
I, Kenneth L. Ross , In a field survey on October 27, 19 97 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			ned s	7	8	Q	to	11	13
current manual of survey ins	structions of the United States Dep	and rules therefore as required in it cartment of the Interior, Bureau of La priner points mentioned in lines 3, 4 and	the "	18	17	16	15	14	1:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

Description of original monument and accessories and/or subsequent restoration: Section Corner for Sections 34 and 35, on the Township Line, T20N-R16W.

1837, Mullett & Brookfield, G.L.O., Boundary Survey Set Wood Post

#1 Beech 10" N 71° E 50 lks.(33.00ft.)
#2 Beech 10" N 77° N 60 lks.(39.60ft.)

1954, Kenneth B. Stephens, RLS \$7318, Mason County Used existing Pipe in Burvey as of Drawing No. K-11

1966, Robert A. Griffin, RLS# 13584
Replaced Iron(no size giving) in the exact
location with a 5" sq. conc. monument, 3 ft
in length. with a 3" brass disk, stamped to
identify this corner. Liber 1, Page 110
#3 Maple 7" N 64° E 92.68 ft.
#4 3/4" x 60" Iron Pipe, Closing Cor. East
6.60 ft.
#5 Boulder 2 feet long, 1.5 ft.wide 1/2
ft. above ground N 45° W 59.18 ft.
#6 Center of 3/4" Iron Pipe, 3 ft. above
ground N 02° E 70.28 ft.
#7 Cedar Post 6" x 7 ft. East 33 ft.
Liber 1 Page 110

19

30

8

10

11

12

13

20

29

32

21

28

33

27

26

35

24

25

36

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

13 Section Corner for Sections 34 and 35, on the Township Line, T20N-R16H.

On October 27, 1997, I Ken Ross and Kevin Pritchard (survey tech.) found a 5" square conc. monument by Robert Griffin as of liber 1 Page 110, corner in 0.5 feet below ground surface at North edge of county road. I found no evidence to dispute the location of this corner.

Condition of record witnesses are; #1 Gone #2 Gone #3 Found in good condition #4 Found in good condition Note: Pipe in now a standard Mason County Monument. #5 Found in good condition, Note found a 39.18 ft, not 59.18' #6 Found in good condition #7 Found in fair condition

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Section Corner for Sections 34 and 35, on the Township Line, T20N-R16W.

I accepted Griffin's 5" square concrete monument, 36" long, with 3" brass cap, stamped to identify the corner, as a substantial marker for the corner, and is accepted as a careful and faithful re-establishment of the position of the original corner.

39.18 E. Camera Ext "BT" #3 Haple 10" N 64° E 92,68 ft. (Ext. 10" dock spike in SE side of tree)
Ext witness #5 Stone 2 ft. long 1.5 ft wide, with "X" chiseled in top N 45° N

Ext witness #6 Iron Ripe 3/4" N 02° E 70.28 ft. top center

Haple 26" N 65° W 61.35 ft. (Bet 60d spike in 75W side of tree)

Closing corner for Sections 2 and 3, T19N-R16W

Signed by_ Surveyor's Michigan License No. 17634

17634 NOV. 5, 1997

15340

Me.

LIBER

4 PAGE 145

Peer Group Reviewed