SURVEY & REMONUMENTATION

MECOSTA COUNTY REMONUMENTATION PROGRAM

APR 0 4 1996

CORNER APPROVED BY PEER GROUP ON MAY 18, 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN COUNTY OF MECOSTA RECEIVED FOR RECORD

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in '95 DEC 19 P1:51 Located in: Corner Code # Mecosta Sec 30 T13N R 09W Public Land Survey A-10 R R R 2. Property Controlling in Section S Miscellaneous Register of Deeds Stamp & File Number Property in Sec. 4. Lot No. , Recorded Plat BCDEF GHI 1 5. Private Claims 2 6 3 2 5 3 , in a field survey on February 1 James J. 4 ٨ 10 12 Keller 11 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 18 13 6 17 -16 15 14 current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 7 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 23 19 20 21 22 24 8 Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: o 10 4 25 30 20 28 27 26 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 31 32 -33 34 35 36 November 13 1837, Abner E. Van Ness, Deputy Surveyor, GLO notes, Set 1/4 Section post, Beech 12" S32°W 12 Links, Beech 8" N48°W 14 Links. November 24 1913, W.W. Willits, County Surveyor, West 1/4 Corner Section 30, Maple 16" N24°E 43', Southwest Corner House N58°E 76', Poplar 12" N16°W 84'

April 13-14, 1916, E.E. Sours, County Surveyor, Field Notes of Survey, (page 8) "Centerline 3rd Street parallel to 1/4 Line 90' South. Line 90' South.

July 27 1982 (L11 P61) (also unrecorded LCRC) G.S. Hackbardt #25844 , Found bolt, 36" Maple N24°E 42.3', SW Corner house N58°E 76', Power Pole N30°W 42.15', Iron 4.6' West & 2.4' North.

1983 Jack Pierson #19305 Found 2" Square Iron, 36" Maple stump N24°W 42.3', SW Corner house N58°E 76', Power Pole N30°W 42.15', 1/2" Iron N17°47'41"W 15.22', Angle Iron Post N25°08'W 17.07'.

June 19 1987, Henry J. Mulder #25862 LCRC (L2 P64) Found Bolt

36" Maple N24°E 42.3', Southwest Corner House N58°E 76.0', Utility Pole N30°W 42.15', Other Iron 4.6' West & 2.4' North Description of corner evidence found and/or method applied in restoring or reestablishing corner: Aug. 2 1989 James J. Keller #10693 Found Bolt 2" Square Head fitting Hackbardt Witness. Found Cut nail Power Pole N38°W 42.18' Found 1/2" Iron N17°W 15.25' approved by mecouta co. Puer ohoup Found Iron Pipe N25°W 13.18' IN ACCORDANCE WITH P.A. 349 of 1990 Found Square 3/4" Iron NW 5.20' Found 1/2" Rebar in center of angle Iron, N28°W 13.06' napp SW Corner of House N61°E 76.20' HAIRMAN Set Nail 6" Maple S42°E 51.09' Found 3/4" Iron Pipe South 90.22' fitting E.E. Sours Description of monument for corner and accessories established to perpetuate locating the position of the corner:

This is accepted as a careful and faithful perpetuation of the position of the original corner. Set Remonumentation corner in Monument Box OF MIC Found Cut nail and Set tag Power Pole N38°W 42.18' Found 1/2" Iron N17°W 15.25' Found Iron Pipe N25°W 13.18'

Found Square 3/4" Iron NW 5.20' Found 1/2" Rebar in center of angle Iron, N28°W 13.06' SW Corner of House N61°E 76.20' Set Nail and Tag 6" Maple S42°E 51.09' Found 3/4" Iron Pipe South 90.22' fitting E.E. Sours

Date __ Signed by Surveyor's Michigan License No.

27 June 1995

JAMIL

KELLEN

LAND

SURVEYOR

No. 10693

OLAND

AD SURVEYORS,

REVISED

REVI FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1983