SURVEY & REMONUMENTATION

## MÉCOSTA COUNTY REMONUMENTATION PROGRAM

WAR 03 1999

CORNER APPROVED BY PEER GROUP ON NOVEMBER 13, 1998

LAND CORNER RECORDATION CERTIFICATE

7 · 5 ···		2 A.C.
JC.	U I I	ON

4 Lot No				···LOGIII,		
1. Public Land Survey  T 16N R 09W G-06  T R T R T R T R T R T R T R T R T R T			EC 28			
2. Property Controlling S T R S IN Section S T R R S IN Section S IN Section S T R R S IN Section S	REGISTER OF DEEDS					
1. JAMES G. KNAPP  do hereby certify that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with relies of the Michigan Board of Land Surveyors or by a Decree of a 7 Court of Law; established, re-established, monumented, re-monumented, receivered, found as expressed below:  NOTE: Only one corner may be recorded on this certificate.  10 NOTE: Only one corner may be recorded on this certificate.  11 DEPUTY SURVEYOR, JOHN HODGSON, SET POST IN SECOND QUARTER 1839. CORNER POST PLACED 40. S.W. CORNER, SECTION 15, AND NOTED, "A BEECH 10" DIAM. FOR QUARTER SECTION POST".  12 ON APRIL 1918, E. E. SOURS, NOTED IN COUNTY SURVEYOR'S RECORD BOOK NO. 1, PAGE 103, SHELM 12" S13°e 62.0' EEECH 16" S39°-30'W 94.2'  13 EEM 12" S13°e 62.0' EEECH 16" S39°-30'W 94.2'  14 CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, DEECH 16" S39°-30'W 94.2'  15 CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, DEECH 16" S39°-30'W 94.2'  16 CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, DEECH 16" S39°-30'W 94.2'  17 CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, DEECH 16" S39°-30'W 94.2'  18 CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, DEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE	er of De	eds St	tamp & F	File Nur	nber	
1, JAMES G. KNAPP  1, in a field survey on  2 do hereby cartify that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in a lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Sanagement of by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:  NOTE: Only one corner may be recorded on this certificate.  10  NOTE: Only one corner may be recorded on this certificate.  11  A. Description of original monument and accessories and/or subsequent restoration: 12  A. Description of original monument and accessories and/or subsequent restoration: 13  BEPUTY SURVEYOR, JOHN HODGSON, SET POST IN SECOND QUARTER 1838, CORNER POST PLACED 40.  S.W. CORNER, SECTION 15, AND NOTED, "A BEECH 1.0" DIAM. FOR QUARTER SECTION POST".  ON APRIL 1918, E. E. SOURS, NOTED IN COUNTY SURVEYOR'S RECORD BOOK NO. 1, PAGE 103, SHE LIM 12" S13°E 62.0'  BEECH 16" S39°-30'W 94.2'  BECH 16" S39°-30'W 94.2'  BECH 16" S39°-30'W 94.2'  CORNER RECORDED AS PER P. R. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, 197 CORNER RECORDED AS PER P. R. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, 197 CORNER MOTED AS, "SET 5/8" RE-ROD WITH R.L.S. CAP 2.5' EAST OF EXISTING CENTERLINE IN LINE WITH FENCE TO WEST AND COUNTY ROAD COMMISSION, BY E. E. SOURS, DATED APRIL 6. SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWES	а в с	C D E	E F G	H 1 3	i K	L
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:  NOTE: Only one corner may be recorded on this certificate.  10  A. Description of original monument and accessories and/or subsequent restoration:  11  12  A. Description of original monument and accessories and/or subsequent restoration:  13  14  15  16  17  18  19  19  19  10  10  10  11  12  21  22  A. Description of original monument and accessories and/or subsequent restoration:  23  24  25  26  26  27  27  28  28  29  29  20  20  20  20  20  20  20  20	6	5	4		2	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Shanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 6 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:  NOTE: Only one corner may be recorded on this certificate.  NOTE: Only one corner may be recorded on this certificate.  NOTE: Only one corner may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  DEPUTY SURVEYOR, JOHN HODGSON, SET POST IN SECOND QUARTER 1838, CORNER POST PLACED 40.  S.W. CORNER, SECTION 15, AND NOTED, "A BEECH 10" DIAM. FOR QUARTER SECTION POST".  ON APRIL 1918, E. E. SOURS, NOTED IN COUNTY SURVEYOR'S RECORD BOOK NO. 1, PAGE 103, SHELM 12" S13°E 62.0'  BEECH 16" S39°-30'W 94.2'  ROAD SURVEY NOTES AT MECOSTA COUNTY ROAD COMMISSION, BY E. E. SOURS, DATED APRIL 6, 19 STA. 84+89.1, WITH THE N.E. AT STA. 58/31.8, AND S.E. AT STA. 111+46.3, SECTION 16, AND STA. 84+89.1, WITH THE N.E. AT STA. 58/31.8, AND S.E. AT STA. 111+46.3, SECTION 16, AND SECONDER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, 197 CORNER RECORDED AS, "SET 5/8" RE-ROD WITH R.L.S. CAP 2.5' EAST OF EXISTING CENTERLINE IN LINE WITH FENCE TO WEST AND OCCUPTION LINE TO EAST", AND WITHESSED:  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 14" ASH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 14" WHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 14" RHITE PIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 14" RHITE PIN SET N	7	8	9		1	12
NOTE: Only one corner may be recorded on this certificate.  **NOTE: Only one corner may be recorded on this certificate.**  **A. Description of original monument and accessories and/or subsequent restoration: DEPUTY SURVEYOR, JOHN HODGSON, SET POST IN SECOND QUARTER 1838, CORNER POST PLACED 40. S.W. CORNER, SECTION 15, AND NOTED, "A BEECH 10" DIAM. FOR QUARTER SECTION POST".  ON APRIL 1918, E. E. SOURS, NOTED IN COUNTY SURVEYOR'S RECORD BOOK NO. 1, PAGE 103, SHELM 12" S13°E 62.0' EEECH 16" S39°-30'W 94.2'  ROAD SURVEY NOTES AT MECOSTA COUNTY ROAD COMMISSION, BY E. E. SOURS, DATED APRIL 6, 19 STA. 84+89.1, WITH THE N.E. AT STA. 58131.8, AND S.E. AT STA. 111+46.3, SECTION 16, AN ELM 12" S13°E 62.0' EEECH 16" S39°-30'W 94.2'  CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, 197 CORNER NOTED AS, "SET 5/8" RE-ROD WITH R.L.S. CAP 2.5' EAST OF EXISTING CENTERLINE IN LINE WITH FENCE TO WEST AND OCCUPPION LINE TO EAST", AND WITHESTS SIDE OF 14" ASH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 14" ASH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE FIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. T	18	17	16	15 1	4	13
A. Description of original monument and accessories and/or subsequent restoration:  BEPUTY SURVEYOR, JOHN HODGSON, SET POST IN SECOND QUARTER 1838, CORNER POST PLACED 40.  S.W. CORNER, SECTION 15, AND NOTED, "A BEECH 10" DIAM. FOR QUARTER SECTION POST".  ON APRIL 1918, E. E. SOURS, NOTED IN COUNTY SURVEYOR'S RECORD BOOK NO. 1, PAGE 103, SH  ELM 12" \$13°E 62.0'  BEECH 16" \$39°-30'W 94.2'  ROAD SURVEY NOTES AT MECOSTA COUNTY ROAD COMMISSION, BY E. E. SOURS, DATED APRIL 6, 19  \$TA. 84+89.1, WITH THE N.E. AT STA. 58:31.8, AND S.E. AT STA. 121+46.3, SECTION 16, AN  ELM 12" \$13°E 62.0'  BEECH 16" \$39°-30'W 94.2'  CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, 197  CORNER NOTED AS, "SET 5/8" RE-ROD WITH R.L.S. CAP 2.5' EAST OF EXISTING CENTERLINE IN  LINE WITH FENCE TO WEST AND OCCUPTION LINE TO EAST", AND WITNESSES DIDE OF 12" WHITE PIN  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE  APPLIANCE OF A STAR OF CENTERLINE OF 150°T.  APPLIANCE OF THE PAGE OF THE P	19	20	21	22 2	3	24
A. Description of original monument and accessories and/or subsequent restoration:  DEPUTY SURVEYOR, JOHN HODGSON, SET POST IN SECOND QUARTER 1838, CORNER POST PLACED 40.  S.W. CORNER, SECTION 15, AND NOTED, "A BEECH 10" DIAM. FOR QUARTER SECTION POST".  ON APRIL 1918, E. E. SOURS, NOTED IN COUNTY SURVEYOR'S RECORD BOOK NO. 1, PAGE 103, SHELM 12" \$13°E 62.0'  BEECH 16" \$39°-30'W 94.2'  ROAD SURVEY NOTES AT MECOSTA COUNTY ROAD COMMISSION, BY E. E. SOURS, DATED APRIL 6, 19  STA. 84+89.1, WITH THE N.E. AT STA. 58:31.8, AND S.E. AT STA. 111+46.3, SECTION 16, AN  ELM 12" \$13°E 62.0'  BEECH 16" \$39°-30'W 94.2'  CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, 197  CORNER NOTED AS, "SET 5/8" RE-ROD WITH R.L.S. CAP 2.5' EAST OF EXISTING CENTERLINE IN  LINE WITH FENCE TO WEST AND OCCUPTION LINE TO EAST", AND WITNESSED:  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 14" ASH  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE  APPLIANCE  BEECH 16" S39°-30'W 94.2'  CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, 197  CORNER NOTED AS, "SET 5/8" RE-ROD WITH R.L.S. CAP I. NORTHWEST SIDE OF 14" ASH  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE  APPLIANCE  BEECH 16" S39°-30'W 94.2'  CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN IN MAPLE  BEECH 16" S39°-30'W 94.2'  CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN IN NORTHWEST SIDE OF 12" WHITE PIN  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE PIN  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" BEECH  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" BEECH  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" BEECH  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 10" WHITE PIN  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 10" WHITE PIN  SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 10" WHITE PIN  SET NAIL W/R.L.S.	30	29	28	27 2	6	25
DEPUTY SURVEYOR, JOHN HODGSON, SET POST IN SECOND QUARTER 1838, CORNER POST PLACED 40.  S.W. CORNER, SECTION 15, AND NOTED, "A BEECH 10" DIAM. FOR QUARTER SECTION POST".  ON APRIL 1918, E. E. SOURS, NOTED IN COUNTY SURVEYOR'S RECORD BOOK NO. 1, PAGE 103, SHE LM 12" S13°E 62.0'  BEECH 16" S39°-30'W 94.2'  ROAD SURVEY NOTES AT MECOSTA COUNTY ROAD COMMISSION, BY E. E. SOURS, DATED APRIL 6, 19  STA. 84+89.1, WITH THE N.E. AT STA. 58:31.8, AND S.E. AT STA. 111+46.3, SECTION 16, AN ELM 12" S13°E 62.0'  BEECH 16" S39°-30'W 94.2'  CORNER RECORDED AS PER P. A. 74 OF 1970, BY JOHN I. NELSON, P.S. 21273, ON JUNE 3, 197  CORNER NOTED AS, "SET 5/8" RE-ROD WITH R.L.S. CAP 2.5' EAST OF EXISTING CENTERLINE IN LINE WITH FENCE TO WEST AND OCCUPTION LINE TO EAST", AND WITNESSED:  SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 14" ASH SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 12" WHITE FIN SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE OF 10 AND ADDRESS OF 10 AND ADDRESS OF 20 TWIN MAPLE OF 20 TW	31	32	33	34 3	5	36
SET NAIL W/R.L.S. TAG IN NORTHWEST SIDE OF 22" BEECH SET NAIL W/R.L.S. TAG IN SOUTH SIDE OF 20" TWIN MAPLE  APPLIA  IN A  DAT  B. Description of corner evidence found and/or method applied in restoring or reestablishing of the state of the	918, NO ND WITN 77, IN 150 <sup>TH</sup>	OTES CONESSED: LIBER AVE.	ORNER AS:  1, PAGE (20' AS  57.1	S BEING E 297, PHALT)	AND	иі
DAT  3. Description of corner evidence found and/or method applied in restoring or reestablishing of cound 5/8" X 18" RE-BAR, IN BITUMINOUS ROAD SURFACE, 2.5' EAST OF CENTERLINE OF 150 <sup>TH</sup> .	AZ LE AZ	Z. 224° Z. 272°	94.2	20'(O.B 90'		ÜB
DAT  B. Description of corner evidence found and/or method applied in restoring or reestablishing of cound 5/8" X 18" RE-BAR, IN BITUMINOUS ROAD SURFACE, 2.5' EAST OF CENTERLINE OF 150 <sup>TH</sup> .	ACCORD	ANCE V	WITH P.A			رجا
FOUND 5/8" X 18" RE-BAR, IN BITUMINOUS ROAD SURFACE, 2.5' EAST OF CENTERLINE OF 150 <sup>TH</sup> .	MLA AIRMAN TE		7. 73	10	100	<u>-</u>
	positio	E (20'  on of th  FUL RE  ONUMEN	ne corne C-ESTABL	FT: .ISHMEN!	r of	in.

LIBER 101 PAGE

Date

48.18 FEET

FORM APPROVED BY MICHIGAN STATE BOARD

DECEMBER 17,

AZ. 268°,

1998

STATE BOARD OF URVEINED AN REVISEO MARKET BOARD FOR WORDING REVISEO AND ADAPTED FOR WORDING RE

of Bichies

SET 60d SPIKE W/REMONUMENTATION TAG IN SOUTH SIDE OF TWIN 36" MAPLE

Surveyor's Michigan License No.