APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

APR 2 8 1995

113

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in	•	•		S	TATE OF HIC	HIGAN		
	MIDLAND (County)	Located In:	Corner Code ##		057	HIDLAND CO ONUMENTATIO		ı Ch	
		4.444			RCF:	MKALICIA I H I T I	NE CE ET	LLU	
1.	Public Land Survey	T14N R1W T R	<u>1-13</u>		11	OCT 94 4	09 P.N		
		T R				retent v a a	TH AVETE		
						BEVERLY J TREGISTER OF		•	
2.	Property Controlling	S T R				WEGTO LEW DI	DEEDS)	
	in Section	S T R							
3.	Miscellaneous	STR		Regis	iter of De	eds Stamp	& File	Numbe	ır
	Property in Sec.	S R		<u> </u>		··· ····· ···			
4.	Lot No, Re	ecorded Plat	·		А В С	DEF	GН	ΙJΚ	
							ΪÏ	i ĭ î	广
				·	2 - 6 -	-5	- i -	ż	
					3				
,	PAUL B. LAPHAM	in a field survey onJULY	: 40 94	4	<u> </u>	-8-1-9-	10-	11	
do		irements of P.A. 74, Michigan P.A			5				Г
in I	ines 1 and 2 above were in	conformance with regulations a	nd rules therefore as require	d in the	7 18	_1716	15	14	
		ctions of the United States Depa Court of Law and/or that the corn			8 _ 1				
ab	ove were in conformance with	the rules of the Michigan Board	of Land Surveyors or by a Dec	cr ee of a			1 22	23-	
	urt of Law; established, re pressed below:	e-established, monumented, re-	-monumented, recovered, fo		10 30				Γ.
		rners, all in the same town a	and range, may be recorde		11	29 28	i i	20-	Γ,
110	on this certificate.	iners, an in the same town t	mu range, may be record		12 31	32 33		75	Γ.
	,		*		13			Ľ	
A.		nonument and accessories ar		on:					
	07/12/72 - David (1) N 60°W, Tag i (2) S 45°E, Tag ii (3) S 50°W. © S.	D' - Power Pole	old witnesses, Set 3/4"	' pipe tC.R.(C. 515				
В.	Description of corner evi	idence found and/or method	applied in restoring or ree	establishing c	orner:	, *			
	I-13: Section Corner Found 3/4" pipe. E: Found recorded With	r on Township line commo xcavated to 2 feet and fo esses 1, 2, & 3	n to Sections 34 & 35 und Metal Bar in Concre	ete		/			
		3			-				
		·							
						•			
				•					
	Accented as hest a	vailable evidence of the po	sition of the original co	rner & renia	ced with	Standard	Monum	nent	
	·		-	•				~	
C.		pproved for remonumentati t for corner and accessories						9_7_7	
	Set 5/8" × 18" re- S 70°E, 134.9 N 60°W, Tag ii S 45°E, Tag in	r on Township line commo -rod with brass cap stam; 3' - Nail & Tag in 15" (n Power Pole, 82.20' (1) n Tele. Pole, 49.22' (2) end, 36" C.M.P., 27.95' (3	ped "Midland Co. Remon Jak	ı. Cor. PS 94	433" in	Monument Destriction PAL LAP		OF THE	TO THE

Surveyor's Michigan License No. 9433

SURVEYOR No.