SURVEY & REMONUMENTATION

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

APR 28 1995

COMMISSION

REMON. COR. D-3, LARKIN TWP.

	11/21/94919		R RECORDATION CE			141	
1. Pub 2. Propin Sc 3. Misc	controlling S co	Located in: T 15N R 2E T R T R T R T R T R T R T R T R T R T R	Corner Code #	Register of Deeds	REGISTER	COUNTY TION & FIL 1:00 P.M. J THAYER OF DEEDS	
4. Lot l 5. Priva	No, Recorded Plat ate Claims			ABC	DEFG	ніј	К L
that under lines 1 are in the cur interior, I corner p of the Mi monume NOTE:	EY CLAYPOOL, in a field survey on FEB 1 er requirements of P.A. 74, Michigan P.A. nd 2 above were in conformance with regreent manual of survey instructions of the Bureau of Land Management or by a description of Land Surveyors or by a lented, re-monumented, recovered, found Not more than 4 corners, all in recorded on this certificate. Cription of original monument and Corner common to Sections 5 and 8 Government survey 1830's, set post Survey by J. Jones, 1987, 1992, 1993, found 1/2' x 2" bar	of 1970, the corner gulations and rules he United States cree of a Court of I we were in conform Decree of a Court of as expressed below the same town	r points mentioned on therefore as required Department of the Law and/or that the nance with the rules of Law; re-established, w:	2	-54	-32 -101 -151222272	——————————————————————————————————————
	Survey by J. Schafer, 1979, found drag	tooth _.					
WITNE	SS NOTE: Witnesses from above presented to peer revi		CRC's are available in de and is on file at the Reg				
B. Des	cription of corner evidence found	and/or method	applied in restoring or	reestablishing co	ner:		
D-3	Corner common to Sections 5 and 8			•			
	Found 1/4" x 4" bar (replaced with 5/8"	rod and brass cap)	per surveys by J. Jones, an	d LCRC by J. Schafer.			
Corner	<u>3</u> was approved for remonu	ımentation at a	Peer Review Committe	e Meeting on	Nov.	<i>Z/</i>	, 192
C. Des	cription of monument for corner a	and accessories	established to perpetu	ate locating the po	osition of the	corner:	
D-3	Corner common to Sections 5 and 8	•					

Found 1/4" x 4"bar (replaced with 5/8" rod and brass cap stamped Midland County Remon. Cor. PS 29241 in mon box) per surveys by J. Jones a LCRC by J. Schafer; and is accepted as the best available evidence of the accepted position of the corner.

\$ 80 Deg W, 141.89', nail and plastic disc in power pole South 96.55', nail and plastic disc in 8" Ash

S 80 Deg E, 241.85', nail and plastic disc in power pole \$ 60 Deg W, 29.54', centerline East end drive tube

Date 11-28-99

Surveyor's Michigan License No. 29241

Form approved by Michigan State Board of I

