## SURVEY & REMONUMENTATION

## APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

Surveyor's Michigan License No. 29241

## APR 2 8 1995

## COMMISSION

149

ul de a a a	REMON. COR. LAND CORNER R	M-3, LARKIN TOWN ECORDATION CER	ISHIP TIFICATE
11/21/94 919	Filing Requireme	nt of Act 74, Mich. F	P.A. 1970
For corners in		·	STATE OF MICHIGAN
Midland (County)	Located in: Co		MIDLAND COUNTY
(County)	Located in: Co	rner Code #	REHONUMENTATION & FILED
Public Land Survey	T <u>15N</u> R <u>2E</u> T R	M-3	28 NOV 94 1:01 P.H.
	T R _		BEVERLY J THAYER
2. Property Controlling S	<u> </u>		REGISTER OF DEEDS
2. Property Controlling S in Section S			
3. Miscellaneous S	<del></del>	<del></del>	
Property in Sec. S	T R -	-	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat _			
5. Private Claims			ABCDEFGHIJKL
i, RODNEY CLAYPOOL, in a field survey on	February 14 19 94 do hereb	v certify	
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on			2 6 5 4 3 2 1
lines 1 and 2 above were in conformance with regulations and rules therefore as required			4 7 8 9 10 11 1
in the current manual of survey instructions of the United States Department of the			
interior, Bureau of Land Management or by a decree of a Court of Law and/or that the			6 - 18 - 17 - 16 - 15 - 14 - 1:
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules			7
of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:			8 -19 -20 -21 -22 -23 -24
monumented, re-monumented, recovered, t	ound as expressed below:		9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
NOTE: Not more than 4 corners, a	all in the same town and	I range, may he	10 -30 -29 -28 -27 -26 -2!
recorded on this certificate.			12 -31 -32 -33 -34 -35 -30
			13 33 34 35
A. Description of original monumen M-2 Corner common to Section 1 and 12 on  Government survey 1830's, set po Survey by I. Leavenworth, 1892, V calls for wood stake deep in gro Survey by J. Schafer, 1974, Found 1 1/2" square wood post 2" raised with 3/4" pipe. Survey by D. Whittier, 1976, Found Survey by J. Jones, 1982 Survey by D. Ledy, 1992, found 3/ LCRC by J. Schafer, 1974,	East Town Line  est  illage of Hubbard,  und  deep,  d 3/4" pipe	,	
found 1 1/2" square wood stake, raised with 3/4" pipe			
WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.			
B. Description of corner evidence for M-2 Corner common to Section 1 and 12 on		lied in restoring or re	eestablishing corner:
Found found 3/4" pipe (replaced v Schafer.	with 3/4" pipe and brass cap) p	per surveys by I. Leavenw	vorth, J. Schafer, D. Whittier, J. Jones, D. Ledy and LCRC1
Corner was approved for rer	monumentation at a Peer	Review Committee I	Meeting on, 19 <i>9c</i>
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-2 Corner common to Section 1 and 12 on East Town Line			
Found 3/4" pipe (replaced with 3/4" pipe and brass cap stamped Midland Co. Remon Cor. PS 29241 in mon box) per surveys by I. Leavenworth, J. Schafer, D. Whittier, J. Jones, D. Ledy and LCRC by J. Schafer and is accepted as the best available evidence of the position of the original corner.			
North 8.97', SE cor Sec 6 T15N-R3	Æ	S 75 Den F 44 95'	, nail and plastic disc in power po
S 75 Deg W, 36.42', nail and plastic disc in 8" Cottonwood N 20 Deg W, 96.59', nail and plastic disc in 6" Elm		S 45 Deg W, 103.7	, nail and plastic disc in power pole 3', PK nail in power pole ', nall and tag in fence post CLAYPOOL

Form approved by Michigan State Board of Land