SURVEY & REMONUMENTATION

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

APR 2 8 1995

COMMISSION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF HIGHIGAN

_	MIDLAND (County)	Located In:			Corner Code ##		KIDLAND COUNTY REMONUMENTATION & FILED								
1.	Public Land Survey			_ R <u>1W</u>	M-7		21 DEC 94 11:19 A.M.								
			Τ	_ R			BEVERLY I THAYER REGISTER OF DEEDS								
 3. 	in Section	s	T T T	_ R		Regi	ister o						Num	ibei	r
	Property in Sec.	s	_ T	_ R	<u> </u>										
		ot No, Recorded Plat								E F	G	н	1 3	ĸ	L
5.	Private Claims					·	3	6	-5-			-3-	2		
1.	PAUL B. LAPHAM	., in a fie	ld survey (n NOVEM	BER , 19 94		5		Ů.	لبا		 	П		_
in cu Ma	hereby certify that under re- lines 1 and 2 above were in arrent manual of survey instrangement or by a decree of anagement or by a decree of any were in conformance were	equirements in conform ructions of faCourt of ith the rule	s of P.A. 74, eance with the the United Law and/or es of the Mic	Michigan P.A regulations at I States Depa r that the corn chigan Board	of 1970, the corner points ment nd rules therefore as required rtment of the Interior, Bureau of er points mentioned in lines 3, 4 of Land Surveyors or by a Decre monumented, recovered, four	ioned in the Land and 5 se of a	6 —1 7 — 8 —1 9 —	9	17 	21-		-22-	23	\- \	—1 —2
ex	pressed below:						10	<u>}</u>	-29	28	+	-27	-26	3 —}	2
NOTE: Not more than 4 corners, all in the same town and range, may be recorded								╂╌╂		+	+	+	\vdash	┪	\dashv

Description of original monument and accessories and/or subsequent restoration:

1852 AUSTIN BURT WIT.-ELM 8" S38W 5 1/2 LKS. B. ASH 7" N16W 9 LKS.

on this certificate.

1909 GIBBS SET LONG BOLT WITH SQUARE HEAD ON TOP 9.89' SOUTH OF CORNER, SECT. 21-28 HUB. (G.L.O. PLAT MAP OF T16N, R1E SHOWS 6.89)

1960 MDOT PLAN 3/4" PIPE IN MON. BOX 450.58'(6.83 CH) SOUTH OF & BAKER ROAD (21.28 SEC. COR.)

6-22-74 JOHN RADCLIFFE L.C.R.C.
MON. BOX IN & MERIDIAN ROAD.
WIT.-(1)TELE. POLE N45W 56.77'
(2)POWER POLE S65W 92.77'
(3)NORTH POST OF ARROW SIGN S88E 22.93'

2-8-88 LEDY, (132) SURVEY FOUND MON. BOX NO WITNESSES

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 5/8"x36" ROD AND UNDER THAT WAS 3/4"x28" PIPE IN MON. BOX. EXCAVATED TO 3' DEPTH. DID NOT FIND FURTHER EVIDENCE. FOUND WITNESSES #1, 2 & 3.

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument.

Corner, M-7 was approved for remonumentation at a Peer Review Committee Meeting on 12-05

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-7; SE Corner common to Section 13
Set 5/8" x 36" re-rod with bross cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box.
WITNESS:
N45"W 56.77' TELE. POLE (1)
S65"W 92.77' POWER POLE (2)
S88"E 22.93' NORTH POST OF ARROW SIGN (3)
© M-30 1.40' WEST

__ Date __

TE OF MICHIGAN PAUL B. LAPHAM PROFESSIONAL SURVEYOR No. 9433 Poressions

Surveyor's Michigan License No. -

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 REVISED MAY 14

REVISED JAN.