LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T S., R W		
2. PROPERTY CONTROLL- 7	,T. 6 S., R. 10 E. A.	-3, A-4, A-5, B-3	
3. MISCELLANEOUS PROPERTY IN SECTION	ľ		
	ORDED PLAT	-	
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in hir re-established, monumented, re-rand rules therefore as required in Bureau of Land Management or	nes 1 and 2 above were, in a field nonumented, recovered or restore in the current manual of survey in by a decree of a court of law. Further, on September 19	survey on Septemical as expressed below and structions of the United Stribermore, that the corner of the structions of the United Stribermore, that the corner of the structure	of P.A. 74, Michigan P.A. of 1970, ber , 19 75, established, in conformance with regulations states Department of the Interior, r points mentioned in lines 3, 4 tored, established or re-established ration for Land Surveyors or, by a
A. Description of original monument and accessories and/or subsequent restoration:			
P. Description of corner evidence	e found and/or method applied i	n restoring or re-establishi	ng corner:
A-4 - Recovered 1/2"			ron Pipe with Cap #18655
A-5 - Recovered 1/2" Iron Rod		B-3 - Set 4" Concrete Monument with Aluminum Cap.	
C. Description of monument for corner and accessories established A-4 1/2" Iron Pipe S59°W, 13.34' Twin 6" Oak, Spike & Tag N83°E, 39.70' Tripe 15" Ash, Spike & Tag N12°E, 26.42' Twin 15" Ash, Spike & Tag A-5 1/2" Iron Rod N01°E, 31.30' Power Pole, Spike & Tag S69°W, 70.44' Anchor Pole, Spike & Tag N39°W, 30.6 East End, 30" C.M.P.		A-3 3/4" Iron Pipe with Cap #18655 S86°W. 8.78', 12" Ash, Spike & Tag	
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN RE	GISTRATION NO		(SEAL)
FOR STATE AND UNITED S	TATES AGENCIES:		
SIGNED BY	CHIEF OF SIEVEV BASTY	DATE	
APPROVED AND SIGNED BY	Sould L Bisse	OATE_	11/6/75
	midnight under some ages.		(SEAL)

PAGE 2