## SURVEY & REMONUMENTATION

County Rep

For corners in MONROE

APR 2 8 1995

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Located In: Corner Code = ++ (County) 7 7 S R 7 E Public Land Survey R R Property Controlling in Section R Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

... Recorded Plat Private Claims 1994 MONROE COUNTY REMONUMENTATION PROGRAM Peer Group approved corner on 9/20/1994 per Act 345 of 1990.

\_ , in a field survey on \_ t. G.B. Warnke, Jr. 9/20/1994\_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	<u>*</u>	В	Ç	O	E	F_	G	H	1 3	K	L	M
2	L	6		5	L	4	L	3—			1	
3	L	$\perp$	_	<u> </u>		<u> </u>	$oldsymbol{\perp}$	$oxed{oxed}$			_	
4	L	ļ 7—	_	8	丄	ا 9.—	<u> </u>	 10	_,	1_		2
5	_		L	$\perp$	<u> </u>	_	ļ	<u>L</u>	L			
6	<u>L</u> .	 18	L	] 17—	L	 16	1_	 15	1	4		
7	L	_	_	1_	L	<del> </del> _	_					
8	<u> </u>	 19⊶—	-	50— [	<u> </u>	 21~-	<u> </u>	 22—	2	3	2	4
9	_	<u> </u>	<u> </u>	_	_	1	$\perp$			Ш		$\Box$
10	L	 30—	L.	 29—-	Ļ	 28		 27—	2	6	2	5-
11	L	ļ	L	L	L	L	$\perp$		_			
12	;	 31—	_	 32	L,	33—	;	} 3 <b>4</b> -	3	5	a	6-
1.3		Ì		1		Ī		1		ı		

A. Description of original monument and accessories and/or subsequent restoration:

F-9, T7S, R7E, Ida Township, Monroe County 7 ID No. 58

Section Corner Common to Sections 20, 21, 28, 29 ( Todd & Douglas Roads - 2" tarby on 15" heavy stone ) 1820, G.L.O. Surveyor, Joseph Wampler, set section post for Sections 20, 21, 28 & 29, Town 7 South, Range 7 East. 1913, L.A. Howard found stone on "Todd Farm" survey in Section 28. Date?, notes from M.C.R.C. used grader and no stone found. 1969, A.J. Marino used PK nail. 1976, G.B. Warnke used found R.R. spike and recorded in LCRC, Liber 2, Pages 134-135. 1977, Road Commission Surveyor found L.A. Howard's 1913 survey on the "Todd Farm" and G.B. Warnke set 3/4" x 30" iron pipe according to said L.A. Howard survey and recorded in LCRC, Liber 2, Page 220.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-9 - 9/15/1994, found 3/4 inch x 30 inch iron pipe set by George B. Warnke, Jr. as pro-rated from an old linen survey by L.A. Howard, dated 1913, on the "Todd Farm". Replaced with 1 inch x 36 inch iron pipe with brass remonumentation cap inside monument box and witnessed as shown below.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9 - Set 1 inch x 36 inch iron pipe with brass remonumentation cap inside monument box to replace 3/4 inch x 30 inch iron pipe and accepted as the best available evidence of the position of the original corner and witnesses:

North 38° East 28.02 feet to nail/shiner in west face of telephone pole

South 35° West 69.65 feet to nail/shiner in northeast face of electric pole

South 48° East 39.62 feet to PK nail in northwest face of electric pole

North 50° West 38.94 feet to nail/shiner in easterly face of telephone pole

North 45° West 35.96 feet to southeast face of gas vent

Signed by 19474 Burveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975