## SURVEY & REMONUMENTATION

## RATIFIED BY PEER GROUP PA 345 OF 1990

APR 28 1995

COMMISSION

MON	HOE					N
date:_	9	20	19	94		)
Count	v Da		$X_{\lambda}$		TT.	

LAND CORNER RECORDATION CERTIFICATE

		Filing Requirement of Act 74, Mich. P.A. 197	n e be 🚟 🔛 🕒
Fo	r corners in	rung nequirement of Act 14, when P.A. 157	
1	ONROE (County)	Located In: IDA TWP. Comer Code =##	23 7
1.	Public Land Survey	T 7 S R 7 E E-10  T R E E-10  T R E E-10	AN IO: 33
2.	Property Controlling in Section	S T R S T R	•
3.	Miscellaneous Property in Sec.	S T R R	legister of Deeds Stamp & File Number

1994 MONROE COUNTY REMONUMENTATION PROGRAM

Peer Group approved corner on 1/20/14 per Act 345 of 1990.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

REVISED MAY 14, 1975

REVISED JAN., 1983

- A. Description of original monument and accessories and/or subsequent restoration:
  - E-10, T7S, R7E, Ida Township, Monroe County ID No. 58 Section Corner Common to Sections 28 & 29 ( Douglas Road 1/2 mile south of Todd Road 8 inch stone mixed with sand to 30 inches )
  - 1820, G.L.O. Surveyor, Joseph Wampler, between Sections 28 & 29 set quarter section post and witnessed: B. Oak 17 inch N.71°E. 253 links & no other trees post in prairie. 1904, L.A. Howard field notes show stone found; and, 1914, Howard survey of "Todd Farm" shows stone found. 1972-1973, M.R. Fleck used F.I.P. on several recorded surveys. 1977, G.B. Warnke recorded L.C.R.C., Liber 2, Page 220, to found iron rod leaning over stone 0.7 feet deep and notes Howard survey.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - E-10 9/20/1994, Found 1/2 inch X 24 inch iron rod leaning over high point 8 inch x 4 inch x 6 inch stone, setting on another limestone slightly larger. Dug to 30 inches deep, 20+ inches diameter. Sand mixed, marbled with black sand. No real evidence of post. Reset 1/2 inch iron rod with 1 inch x 36 inch iron pipe with 4 inch x 10 inch steel pipe at base and piece of stone on north and south side at 20 inches deep and witnessed as shown below. 9/29/1994, set brass remonumentation cap on 1 inch x 36 inch iron pipe.
- ■C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - E-10 Set brass renommentation cap on 1 inch x 36 inch iron pipe with 4 inch X 10 inch steel pipe at base and piece of stone on north and south side at 20 inches deep and is accepted as the best available evidence of the position of the original corner and Witnesses:

North 40° Fast 55.70 feet to nail in west face telephone pole

South 25° West 124.49 feet to nail in easterly face electric pole

South 20° East 118.00 feet to nail in westerly face telephone pole

South 75° West 97.8 feet southeast corner of foundation

(///2)	
Bigned by	Date9/29/1994
19474	
Europyor's Michigan License No	ECOM APPROVED BY MICHIGAN STATE ROARD OF LAND SURVEYORS. JAN. 28, 1971