			•			
	manager at the fi	·			Section 1	_
						1
RATIF	FIED BY PEER GROUP					
ļ	PA 345 OF 1990					
	E COUNTY, MICHIGA				e Si m	
	9120194	LAND COP	RNER RECORDATION CE	ERITICATE	高。 高品。	
County R For corners		🤰 💢 Filing Req	uirement of Act 74, Micl	h. P.A. 1970	- 실정성 - 범트림	
Monroe (1		
	(County)	Located In:	Corner Code ##	}		
	,					
1. Publić Whitefor	Land Survey	T 850	FF C-A		46. S	
. WILL CETON	tu jap.	T R			3 (3)	
			REM <u>ONUMENTAT</u>	ichi :		
•				>		-
in Sect		T R T R		Operiotes	at Danda Otawa A Mila i	
	ty in Sec. S _	T R	- 31: 11 3-3 1330	register	of Deeds Stamp & File I	Number
	<u> </u>		COMMISSION			
	, Record			<u> </u>	BCDEFGH	I J K
5. Private	Claims			2	6543	L 2
George E	3. Warnke, Jr. Cornei		•	3		
				4	·	- -11
I, G.B. WAF	NKE, JR. in a	field survey on	1994 & 1995	mentioned	╅╅╂╂╅┪	┝┼╌┼
in lines 1 ar	nd 2 above were in confo	rmance with regulation	s and rules therefore as requi	red in the	-18171615	1 4
			epartment of the Interior, Burea orner points mentioned in lines			
above were	in conformance with the r	ules of the Michigan Boa	ard of Land Surveyors or by a D	ecree of a	19-1-20-1-2122	53
Court of La expressed b		olished, monumented.	re-monumented, recovered,	found as	30 29 28 27	26
NOTE: No	ot more than 4 corners	, all in the same tow	n and range, may be record	ded 11		
, '	this certificate.			12	313234	35
A Descri	ntion of original monum	ant and accessories	and/or subsequent restora	13		LL.
1820, G. 31 links 1 1/2' h north.) L. 1, Pg chief, M G.B. War N.10°W.	I.O. Surveyor, Josep & R. Oak 11 \$78°W 4 below road raised wit 1971, A.J. Marino r J. 233, to 1 1/4" iro fax W. Walter recorder mke: 1978 - found in 16.95 feet; 1989 - f	oh Wampler, between 19 links. 1965, M.S. In 1/4" pipe. (No notes F.I. and with m pipe. 1972, G.B. In	(U.S. 223 & Sylvania Pe Sections 9 & 10, set qt .H.D. survey chief, Jess te - 1966 plans show con esses same as M.S.H.D. . Warnke found 1 1/2" ir Pg. 1 & 2, found 3/4" ir box and witnessed monum comment box and notes mo L. 3, Pg. 232, to found od applied in restoring or re	er. sec. post & wise M. Carlson, four struction center 1972, Kenneth Suyron pipe. 1975, Moon pipe at levelment box in center nument box in center on the second sec	tnesses: Elm 9 \$23°E md 3/4" pipe, ine to be 15.93' dam recorded LCRC, 1.D.S.H. & T. survey with Bit. surface. cline of pavement aterline 15.95'	
G-4 - 8/ 9/20/94	3/1994, found 1/2 ir - corner was Peer Gu	nch iron pin (flare roup approved. 9/2	d top) in monument box a 8/95 — set yellow plasti	nd witnessed as s c remonumentation	shown below. I cap on found pin.	
_	•					
			•			
	•					
·					• .	
			.•	**		
C. Descri	ption of monument for	corner and accessori	es established to perpetua	te locating the posi	ition of the corner:	•
the best North 30 North 30 South 40 North 3.	c available evidence P West 114.07 feet to P East 94.20 feet to P West 66.25 feet 16 7 feet to south edge	of the position of to nail/shiner in ear nail/shiner in we hall in east face of concrete pavements.	e of electric pole ent	witnesses: e	and is accepted as OF MARSHEE, WARSHEE,	B
North 20	west 16.93 feet to	monument box for o	centerline control of U.	s. 223	LAND SURVE 10%. 104.4	. *
	Х	10)//=	- Jan	12 /19/19	Mary College	CONTRACTOR OF THE PARTY OF THE
Signed by		January 1	Date	10-71 (713	THE CHILD	50
Surveyor's	Michigan License No.			FORM APPROVED BY M	IICHIGAN STATE BOARD OF LAND SURVE	

UMM 4 FADE 1.00