SURVEY & REMONUMENTATION

APR 28 1995

RATIFIED BY PEER GROUP MONROE COLLEGY ALCHIGAN.

COMMISSION

RECEIVED FOR RECORD

94 DEC 29 /HII: 07

County Rep.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1. 1.	
fori allen	
REGISTER OF DEEDS MUNROE COUNTY, MICH	
THE COURT OF THE PROPERTY OF	1

For corners in MONROE Located In: BEDFORD Corner Code ## (County) T8SR7E 1. Public Land Survey T _____ R ____ T R T R _ Property Controlling __ T ____ R __ __ T ____ R _ in Section ___ T ____ R __ Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat							
5.	Private Claims							
	1993 MONROE COUNTY REMONUMENTATION PROGRAM Peer Group approved corner on 11/16/1993 per Act 345 of 1990.							
l	G.B. WARNKE, JR. in a field survey on 12/14/1994							

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	<u>^</u>	<u>B</u>	C	0	E	F	G	Н	IJ	K	L	M
2		6—	L	5	L	4	L	3 —	2		Ĺ	
3	_	<u> </u>	_	 _	<u> </u>		\perp	1		_		<u>L</u>
4	_	ļ	_	 8	L	9	丄	 10	,		1	2-
5		_	_	<u> </u>	_	<u> </u>	↓_	.	\sqcup	_	_	_
6	1	 8	 	 7	<u> </u>	 6	\downarrow	 15	 14	_	1	3
7	_	_	<u> </u>	ļ	ļ	<u> </u>	_	↓_		_		
8		 9		 20—		 		 22	23	\dashv	—- 2	4-
9	_	1	 		_	<u> </u>	<u> </u>	1				
10	:	 30	<u> </u>	و	L	 8—	_	 27	26	\dashv	2	5
11	<u> </u>	<u> </u>	L	1_	<u> </u>	_	<u> </u>	$oxed{oxed}$		_		_
12	-:	\ 31	 	2	Ļ	3	<u> </u>	34	35	_	3	6
13	L_		<u>L</u>	1_	L_	_	<u> </u>		Ш	\perp		

- Description of original monument and accessories and/or subsequent restoration:
 - E-9, T8S, R7E, Section Corner Common to Sections 20, 21, 28 & 29 (At Dean & Douglas Roads) 1820, G.L.O. Surveyor set corner post at Sections 20, 21, 28 & 29; witnesses: B. Oak 11 (inch) S.68° W. 8 links & B. Oak 10 (inch) N.68°E. 36 links. / Witness card notes found stone in 1948 with 4 witnesses (none remain). / 1911, J.W. White survey notes stone - no witnesses. / G.B. Warnke set bolt over stone about 1975. / Rolf Goerlich, former crew chief for M.R. Fleck, stated that they used the stone. / The plats of Douglas Village 1 & 2 were from the stone. / Several surveys by G.B. Warnke have occupied this corner. / 1979, A.J. Marino survey used an i.rod 2.86 feet north of holt over stone. This iron hasn't been found for several years.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - E-9 On 10/29/1993, found 2 inch square bolt 3 1/2 inches deep and set 1/2 inch by 2 1/2 inch hex bolt with washer over found bolt and re-witnessed. 12/14/1994, set 1 inch x 36 inch iron pipe with brass remonumentation cap inside monument box to replace bolts.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9 - set 1 inch x 36 inch iron pipe with brass remonumentation cap inside monument box to replace bolts and is accepted as the best available evidence of the position of the original corner and witnesses:

North 45° West 45.28' found nail/shiner in east face of telephone pole

North 45° East 45.45' found nail/shiner in northwest face of telephone pole

South 50° West 61.74' top nut of hydrant South 45° East 46.25' found nail/shiner in north face of utility pole

OF MICHIG GEORGE B. warnke, Jr. LAND SURVEYOR NO. 19474 NSED. LAND

Signed by 19474 Surveyor's Michigan LicenseWo.

12/14/1994 Date

4 D Q