SURVEY & REMONUMENTATION

MATIFIED BY PEER GROUP PA 345 OF 1990 MONROE COUNTY, MICHEAN date: 9 50 1994

5. Private Claims

expressed below:

APR 2 8 1995

COMMISSION

LAND	CORNER	RECORDATION	CERTIFICATE
em : 1 :			

,	County Hopxzxe				
For corners in		Filing Requi	Filing Requirement of Act 74, Mich. P.A. 1970		2 교
	MONROE	Located In:	Corner Code =##		5 월
	(County)	ERIE '			7.1
1.	Public Land Survey	T 8 S R 8 E	A-7		
		T R			
		T R			
2.	Property Controlling	T R S Ti R		in (n N	98
	in Section	S T R			ega e
3.		S R		Register of Deeds Stamp &	Eila Number
	Property in Sec.	S T R		J. J	- The Ivalliber
4.	Lot No.	Recorded Plat			

1994 MONROE COUNTY REMONUMENTATION PROGRAM	1						
Peer Group approved corner on 9/20/1994 per Act 345 of 1990.							
I. G.B. WARNKE, JR. , in a field survey on	8/30/1994	19					
do hereby certify that under requirements of P.A. 74, Michi	igan P.A. of 1970, the come	rocints mentioned					
in lines 1 and 2 above were in conformance with regula	ations and rules therefore	as required in the					
current manual of survey instructions of the United State	es Department of the Interio	or, Bureau off and					
Management or by a decree of a Court of Law and/or that the	he corner points mentioned	dinlines 3 4 and 5					
above were in conformance with the rules of the Michigan	a Board of Land Surveyors	or by a Decree of a					
Court of Law, established, re-established, monument	ted, re-monumented, rec	overed, found as					

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: A-7, T8S, R8E, Errie Township, Monroe County - ID No. 58

Section Corner Common to Sections 18 & 19, T8S, R8E & 13 & 24, T8S, R7E

(Temperance & Minx Roads - hard surface) (Common to M-7, T8S, R7E - Approved 11/16/1993)

1820, G.L.O. Surveyor Joseph Wampler set post on east range line between Sections 13 & 24, T8S, R7E, and witnesses: B. Oak 14 inch S.74°E. 65 links. & Ash 11 inch S.47°W. 58 links. 1953, A.J. Marino survey notes found old rotted cor. post stub with stone on top. Surveyors have used the corner since atleast 1972 with no apparent dispute. 1973, G.B. Warnke excavated and found R.R. spike over stone. 1973, Mannik, Schneider & Associates, Job No. 73025, recorded in Liber 647, Page 616, notes found sandstone. 1973, James T. Bauer recorded L.C.R.C., Liber 1, Page 311, to sandstone monument. 1982, G.B. Warnke recorded L.C.R.C., Liber 2, Page 474, to R.R. spike over stone.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-7 - 11/08/1993, Found Railroad Spike Over Stone. 8/30/1994, replaced points with set 1 inch x 36 inch black iron pipe with brass remonumentation cap, for M-7, T8S, R7E approved 11/16/1993 by Peer Group, inside monument box.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - A-7 Set 1 inch x 36 inch black iron pipe with brass remonumentation cap inside monument box to replace railroad spike over stone & is accepted as the best available evidence of the position of the original $\dot{}$ corner & Witnesses:

12/2

South 39° West 43.58 feet to U.S.G.S. brass plate (TT-1L? - cannot read clearly) on "+" in triangle (leaning to northwest)

South 44° West 39.31 feet to found nail/aluminum shiner in northeast face of telephone pole

North 36° West 44.10 feet to nail/shiner in southeast face of telephone pole

North 45° West 47.44 feet to found 3/4 inch iron pipe in west bank of road ditch

North 60° Fast 100.29 feet to found nail/shiner in southwest face of telephone pole

Signed by Date 9/21/1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1974 REVISED MAY 14, 1975

3 mm/ 399

Surveyor's Michigan License No.