

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Montcalm COUNTY


T 9N. R 7W

DESCRIPTION OF CORNER N 1/4 CORNER Sec. 27

CORNER MONUMENT Railroad Spike

DATE MONUMENT ~~PLACED OR RESTORED~~ Recovered 11-5-69

WITNESSES TO CORNER..... N 83° E. 154.70 A clump of Three 8" maples



S 24° W 79.6 Road Sign Post

South 20.0' Road & Fenwick Rd.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found Railroad Spike at Intersection of
Amsden and Fenwick Roads.

SURVEYOR'S SEAL

SIGNED

[Signature]
REGISTERED LAND SURVEYOR

DATE

7 Jan 70

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68