## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

Montanim COUNTY
T 9N R 7W

DESCRIPTION OF CORNER _	N. E. CORNER	Section	27
CORNER MONUMENT	At Spike		
DATE MONUMENT PLACED AND	WITNESSED//-	-69	
WITNESSES TO CORNER	S. 9-30'E.	40.69	Power Pole
N X			Fence Cor. Post
	AND		
CIRCLE CORNER REGISTER	AND	42.59	Fence Cor. Post

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found Boat Spike At Intersection of Fenwick and Carlson Rds.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

DATE Tranks

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68