## MONTCALM COUNTY REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  Montcalm (County)	iontcalm Located in:			Corner Code #			STATE OF MICHIGAN MONTCALM COUNTY RECORDED						
1. Public Land Survey	Sec 4	T 11N R 7 W	G-2	G-2, E 1/4			17 DEC 1998 2:12:02 PM						
TR						LORI A. WILSON REGISTER OF DEEDS							
2. Property Controlling S T R S S T R							REDISTER OF DECUS						
Miscellaneous     Property in Sec.	3. Miscellaneous S T R Register of Deeds Stamp & File Number Property in Sec. S T R												
4. Lot No, Ro	ecorded I	Plat				۱ ,	В	D I	F 6	; H ;	JK	l. M	
. Trivate olamo					:	2	6	··· 5····	4	3. ·	. 2	ŀ	
I, William Tingley a field survey on October 31, 1995 and hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						4	7	.8	9	10	11	12	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land						5 6	18	17	16	15	14	13	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as						7 8	19 .	- 20	- 21	22	23	24	
expressed below:						9 10	30	29	28	27	- 26	25	
NOTE: Not more than 2 on this certifica		, an in the same tow	m and rang	e, may be re	corded	11 12	- 31	32	33	34	35	36	
Beech 6" December 1869, Henry C Pine 34"	rookfield N21°W S24°E Caulkin, I N61°E	, Deputy Surveyor, ( 12 links 20 links Deputy Surveyor Lib 63 links	GLO Notes er 3, Page <sup>-</sup>	10.	ACCEP GROU PUBLIC	TED I P AS C ACT	BY THE	MONTO FICIAL 1990 AT	ALM CORNE CORNE A MEET	DUNTY IR UND ING HEI	SURVEY DER MIC LD <u>-4/1/</u>	PEER HIGAN	
1884, preserved by New Set Fire Clay Monume Elm 12"	nt and Bl	acksmith Cinders	i, Page 307	, Record or	williates of Safv	еу		Will	iam Ting	ley, PS,	Chalrma	Λ	
Elm 5"	N89°E S32°E	97 links 86-1/2 links							annini.	semitivity)	IIIRore.		
Elm 5" S	crocken ment 189°E 332°E r evidenc le Spline	y from Bearing Tree 97 links 86-1/2 links e found and/or metho .3 feet below road s	Pine Stum d applied in	p N61 restoring or i	reestablishing co	3 lini rner: nes:	t of sto	* Lices	PROF SU	LLIAM INGLE ESSIC RVEYO NO.	Y ONAL	William Willia	
C Description of manu	macksiiiii	corner and accessorie	e clay mon	ad to namelu	ate locating the	nositi	on of th	ne com	er PROF	ESSION	WI SHAME	,	
C. Description of monu- Set Remonumentation & Found Nail in Southea			ument S40°W	51.24 feet		JOSILI	O11 O1	10 0011	OI				
Found Nail in North sid Set Nail and Tag South Set Nail and Tag East	n side Po	wer Pole	S70°E N75°W N20°W	48.38 feet 72.42 feet 82.60 feet		Libe	<sub>er</sub> 4	Page s	37				
This corner is accepted			etuation of	the position	n of the original	corn	er						
Signed by 6200	<u> </u>	Q/ us	Cec	Date _	4/16/	, 1	998						
Surveyor's Michigan Licer	nse No	30104			FORM APPE	₹	Y MICHIO				REVISE	N. 28, 1971 MAY 14, 1976 ED JAN., 1963 MARCH, 1993	
								ALL		.,und FR			

374

SURVEY & REMONUMENTATION

FEB 1 9 1999

SECTION