| ć | ε | D | 1 | Q | 19  | 94 |
|---|---|---|---|---|-----|----|
| _ | _ | _ |   |   | 141 |    |

## MONTCALM COUNTY REMONUMENTATION PROGRAM

Corner approved by Peer Group on \_\_\_\_\_\_

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

| For corners in   |  |
|--|--|
| Montcalm Located In: Corner Code #   | STATE OF HICHIGAN  |
| · ·  | MONTCALK COUNTY  |
|  | / RECORDED   |
| 1. Public Land Survey Sec 31 T 12 R 10 A-13, SW Corner   |  |
| T_11 R_10  | 17 AUG 94 3:49 P.N.  |
| ŤŘ   |  |
| 2. Property Controlling ST_R   | VIRGINIA L. KNEPPER  |
| in Section S T R   | REGISTER UF DEEDS<br>Register of Deeds Stamp & File Number                                 |
| 3. Miscellaneous S T R   |  |
| Property in Sec. STR   |  |
| 4. Lot No, Recorded Plat   |  |
| 5. Private Claims  | A B C D E F G H I J K L M  |
|  | 2 6 5 4 3 2  |
|  | 3  |
| I. <u>William Tingley</u> a field survey on <u>June 22, 1</u>  | 994 4 7 8 9 10 11 12   |
| do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points   | mentioned 5  |
| in lines 1 and 2 above were in conformance with regulations and rules therefore as requirement manual of survey instructions of the United States Department of the Interior, Bureau |  |
| Management or by a decree of a Court of Law and/or that the corner points mentioned in lines   | 3, 4 and 5 7   |
| above were in conformance with the rules of the Michigan Board of Land Surveyors or by a I   |  |
| Court of Law; established, re-established, monumented, re-monumented, recovered, expressed below:  | Tourid as 9  |
|  | 10 30 29 28 27 26 25   |
| NOTE: Not more than 4 corners, all in the same town and range, may be record on this certificate.  | ded 11   |
| on this conficate.   | 12 31 32 33 34 35 36   |
| A. Description of original monument and accessories and/or subsequent restoration  | n: 13  |
| June 9, 1837, Hodgson, Deputy Surveyor, GLO Notes  |  |
| Set Post. White Oak 18" N56°E 43 links   |  |
| White Oak 12" S35°W 71 links   |  |
| May, 1881, F.A. Palmer, Page 283, Book 1, County Survey Book, Montcalm Coun  |  |
| The proper point I found several inches of the old corner stake. It correspond   |  |
| been a resident there for several years and knew the place where the stake st  | ood. Set a gas pipe and norseshoe and broken   |
| of glass.  |  |
| May, 1907, J.F. Daoust, County Surveyor, Book 3, page 336, 337   |  |
| Found Plow Point, Stone and Crockery from Oak 9" S41-1/2°E 88-1/2 links New Bearing Tree: Oak 16" S6-1/2°W 160-1/2 links   |  |
| October, 1908, J.F. Daoust, Notes, Page 78-79  | ADDERTED BY THE MONTON IN A COMMISSION   |
| Same as above.   | ACCEPTED BY THE MONTCALM COUNTY SURVEY PEEF<br>GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN |
| R.D. McNutt's Index Cards, 11-10   | PUBLIC ACT 345 OF 1990 AT A MEETING HELD 22 2 9  |
| White Oak 18" N56°E 43 links White Oak 12" S35°W 71 links  | (10) - (01)  |
| Oak 9" \$41-1/2°E 88-1/2 links   | William Tingley, PS, Chefman   |
| Oak 16" S6-1/2°W 160-1/2 links   | Wallatin Lingley, PS, Chellman   |
| F.A. Palmer 1882, gas pipe, Horseshoe, Glass   |  |
| <ul><li>1908, found plow point, stone, crockery</li><li>B. Description of comer evidence found and/or method applied in restoring or reest</li></ul>                                 | ablishing corner:  |
| Found 1/2" Rerod at surface.   |  |
| 18" deep, found broken plow point  | LIBER 3 PAGE 105   |
| 20" deep, found glass/crockery 24" deep, found 1-1/2" gas pipe in nest of stones   | LIBER J PAGE IVI   |
| Found Nail Northwest side Power Pole S45°W 87.32 feet  |  |
| Found Nail Northeast side 10" Twin Oak N50°W 43.39 feet  |  |
| C. Description of monument for corner and accessories established to perpetuate le   | ocating the position of the sorper   |
| Set Remonumentation Corner and Monument Box over pipe Found Nail Northwest side Power Pole \$45°W 87.32 feet   | * 14/11  |
| Found Nail Northeast side 10" Twin Oak N50°W 43.39 feet  | * WILLIAM G. * TINGLEY *   |
| Set Nail Southside 12" Cherry N85°W 66.96 feet   | O PROFESSIONAL CE  |
| Top Center Riser Box N45°E 55.40 feet  | NO.  |
| Top Center Riser Box S45°E 65.07 feet 7 feet West of Centerline North-South Road   | 10 10 00 104 1 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1   |
| Centerline Road to East  | the original corner  |
| This corner is accepted as a careful and faithful perpetuation of the position of  | ure original content   |
| Signed by (1) com / congly Date Z?   | Jaly , 1994  |
| Surveyor's Michigan License No. 30104  | FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971                     |
|  |  |