SURVEY & REMONUMENTATION

AUG 3 1 1994

Corner approved by Peer Group on									,	1994				
COMMISSI	CORDATION	I CERTIF	ICATI	=										
		F	iling Requ	iremen	t of Act 74, N	/lich. P.A	. 1970	l						
For corners in														
Montcalm (County)		Located In	1:	Corner Code #						STATE OF NICHIGAN MONTCALM COUNTY				
										RECORDED				
Public Land Survey	Sec 9	T <u>12</u> F	₹		G-4, E 1/4					17 ÁL	IG 94	3:47 P	.н.	
		T R T R				-								
2. Property Controlling in Section				VIRGINIA L. KNEPPER REGISTER OF DEEDS										
3. Miscellaneous		TR _TR					Re	giste	r of D	eeds S	Stamp	& File I	Numbe)r
Property in Sec.		F												
4 1 -4 N - F		71-4												
 Lot No, F Private Claims 								1 /	\ B	C D	E F	G H	I J K	L
o. I mate ofamile	.							2	6	5	4	3	2	l i
								3				<u> </u>	ļ	₩.
I, William Tingl	ey		a field s	urvey on _	June 21	L. 1994	,	4	7	8	9 ∢	10	11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the								5						┼.
current manual of survey in Management or by a decree	structions	of the United	l States Dep	partment (of the Interior, B	lureau of l	_and	6 7	18	17	16	15	14	13
above were in conformanc	e with the	rules of the I	Michigan Boa	ard of Lan	d Surveyors or I	by a Decree	e of a	8	19	20	21	22	23	24
Court of Law; establishe expressed below:	eu, re-est	abiisned, m	onumentea,	re-monun	nentea, recove	rea, rouria	as	9						
NOTE: Not more than	4 corners	, all in the	same town	and ran	ge, may be re	corded		10 11	30	29	28	27	26	25
on this certific	ite.							12	31	32	33	34	35	36
A. Description of origin					sequent restor	ration:		13 l		<u> </u>	<u> </u>	<u>.</u>	L	
November 1838, Enoch Set Post	Hammil,	Deputy Su	rveyor, GL	O Notes			:							
Beech 9" N45°V	/ 71 link					ACCEPT GROUP	ED BY THE	THE N	IONTO ICIAL	CORNE	DUNTY ! IR UND	Survey Er Mic	PEE:	
Beech 15" S23°E			i Book Boo	o 57		PUBLIC /	ACT 345	OF 19	90 AT	A MEET	ING HEL	<u>0.24</u>	Jest.	7 3
1892, H.M. Caulkins, County Surveyor, Field Book Page 57 Pine Stump 26" S45°W 32 links									U), ((]		\ \ /	
Pine Stump 24" S64-1/2°E 34-1/2 links November 1895, H.M. Caulkins, County Surveyor, Book 2, Page 46									Will	am Ting	ley, PS,	Chairma	N	
Put down roundish st						der it								
June 1981, T.E. Mueller, Found Shaft in Monur		1, Recorde	ed Survey,	Liber 54	0, Page 1270,	Montcaln	n Coun	ty R	egiste	er of De	eeds			
Top centerline North		ert under d	irive Norti	neast 30	3.8 feet				***					
Nail and cap in 18" C			68.58 feet					LIBE	r 🎝	PAGE .	115			
Nail and cap in Powe Nail and Cap in 20" (62.00 feet 1west 91.1	1 feet										
June 1981, T.E. Mueller					ontcalm Cou	nty Regis	ter of [Deed	s					
Same as above.														
B. Description of come Found 1-1/2" Iron Axle	20" Long	in Mon Bo	x	applied ii	n restoring or r	eestablish	ning co	ner:						
Found remains of 4" > Found 1/2" I.D. Iron pi				remains	of cedar stal	ce 2.3 feet	t deep	bene	ath s	olid ird	on			
Found Nail and tag #1	4769, No	rtheast sid	e 30" Oak \$	Stump 1	N55°W 91.15	feet								
Found Nail and Tag #	14/69 in I	ower Pole	S45°W	61.95 fe	et ·									
C. Description of monu	ment for c	corner and a	accessories	establist	ned to perpetua	ate locatin	g the p	ositic	n of t	he co <u>rr</u>) 	HITTING.		
set kemonumentation (South Wil	a moname	nt Box ove	r cedar s	take.		•			ATTENTIFIE TO	TE OF	MICHIO	ANTA .	
Set Nail Northside Nail & Tag #14769 No			ak Stump	N55°W	91.15 feet				Á	* .	****		V M	
Centerline of Easterly	16" Twin	oak Stum		N89°W	91.05 feet					* *	WILL!/ TING	NG."	*	Ĺ
Nail and Tag #14769 is	1 Power F	'ole		S45°W	61.95 feet				£.	Ęį	PROFFE	and I		į

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Surveyor's Michigan License No.

MONTCALM COUNTY REMONUMENTATION PROGRAM

30104 3076ESSIONE SAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993