LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
	10 T. 12 8, R. 8		ω (ω
2. PROPERTY CONTROLI ING IN SECTIO	10,T. 12 N. R. 8	\$ 5-H	
3, MISCELLANEOUS PROPERTY IN SECTIO	N ,T S., R	E. W.	
4. LOT NO	, RECORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
restored as expressed be of survey instructions o court of law. Further the survey instructions of the	1972, estable low and in conformance with the United States Department of that the corner points of found, recovered, restored	ertify that under requirements of (identified with circles on index ished, re-established, monumente regulations and rules therefore a at of the Interior, Bureau of Land ts mentioned in lines 3,4 and 5 red, established or re-established of Registration for Land Surveyo	ed, re-monumented, recovered or sequired in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in con-
A. Description of origin	al monument and accessories	and/or subsequent restoration:	
34 Iron	Rod	od applied in restoring or re-estab	lishing corner: Lealon Courty Rd. Com
C. Description of monu 3/4" IRON		ies established to perpetuate loca	ating the position of the corner:
S. 52° W.	70.8 Twin 40.4 Road NA 49.2 Stop Si 35.9 Telephon	me Sian	
SIGNED BY.		DATE 5	1-20-72
SURVEYOR'S MICHIGA	n registration no.	2029	(SEAL)
FOR STATE AND UNIT	ED STATES AGENCIES:		
SIGNED BY	CHIEF OF SURVEY PARTY	DATE .	
APPROVED AND SIGNE	D BY. MICHIGAN REGISTER	RED LAND SURVEYOR DATE	(SEAL)