LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

			1 1
FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	1 tean
1. PUBLIC LAND SURVEY.	9. T. 12. N. R. 8. W.	3-F	Montesty V
2. PROPERTY CONTROLL	9 T. 12 N. R. 8 W.	3-F	Con
3. MISCELLANEOUS PROPERTY IN SECTION	N. S., R W.		
4. LOT NO	, RECORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 1921, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1972, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found Monument Box in Road Intersection Cerith 2" Pipe in box			
C. Description of monu	ment for corner and accessories	established to perpetuate loc	cating the position of the corner:
5.30° E.	594 Telephon	a Pole	
SILOF	625 Buried Ca	1010 1114	
N. 76 E.	68.5 Stop Sign 30.0 Rond NAMO	7	
N. 50° W.	30.0 Road NAMO	5 51417	
5.84° W.	54.6 Apple tece	.	1-62-01
SIGNED BY	<u></u> -		-30-92
SURVEYOR'S MICHIGAN REGISTRATION NO. 12029 (SEAL)			
FOR STATE AND UNITED STATES AGENCIES:			
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGN	ED BY MICHIGAN REGISTERED I		(SEAL)