SURVEY & REMONUMENTATION

MAY 07 1997

COMMISSION

MONTCALM COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Montcalm (County) | Located In: Winfield Township | Corner Code #

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED

12/27/1996 2:08:23 PM

VIRGINIA L. KNEPPER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey	Sec 26 T 12N R 9W		J-9, N1/4 Corner
	T___ R___		
	T___ R___		
	T___ R___		
2. Property Controlling	S___ T___ R___		
in Section	S___ T___ R___		
3. Miscellaneous	S___ T___ R___		
Property in Sec.	S___ T___ R___		

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William Tingley a field survey on December 4, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1838, Abner Van Ness, Deputy Surveyor, GLO Notes
38.96 chains Set quarter Section Post
Red Oak 24" N7.5°W 6 links
Beech 6" S7.5°E 10 links
1898, Henry Caulkin, County Surveyor, Liber 2, Page 66, Record of Minutes of Survey
Took New Bearing Tree
Pine Stump 30" N18°E 117 links
1904 Henry Caukin, County Surveyor, Liber 2, Page 55, Record of Minutes of Survey
Found Plow Point and took New Bearing Tree
Pine Stump 24" N61°W 47.5 links
1913, R.D. McNutt, County Surveyor, Index Card File Records.
Stake and Plow Point
Pine 10" N68.5°W 40.5 feet (RDM)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Rerod below the Road .3 feet and on the North Side of the Road and on the Centerline of a two track Road North. At 1.0 feet deep, found remains of Old Wood Stake on the South Side of Rerod.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Remonumentation Monument over Remains of Stake

Found Nail South Side Poplar 12"	N45°W	27.80 feet
Found Nail West Side Pine 12"	N25°E	38.38 feet
Found Nail West Side Poplar 14"	N35°W	38.24 feet
Set Nail and Tag East Side of 6" Pine	S12°E	45.30 feet

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William G Tingley Date 12-17, 1996

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

STATE OF MICHIGAN
WILLIAM G. TINGLEY
PROFESSIONAL SURVEYOR
NO. 30104

ACCEPTED BY THE MONTCALM COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 12-17-96

WGT

William Tingley, PS, Chairman