## DEC 19 2000

## MONTCALM COUNTY REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE

## Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in  Montcalm (County)	Located In: Corner Code # STATE OF MICHIGAN MONTCALM COUNTY										
Winfield Township			:	RECORDED 7 NOV 2000 3:12:57 AM							
					LORI A. WILSON						
1. Public Land Survey Sec. 25,36	T 12 N R 09 W T R T R T R	L-11			<u>REĞİSTI</u>	R OF D	EEDS				
2. Property Controlling S in Section S	_ T R		Registe	er of De	eeds S	tamp 8	. File N	lumbe	r		
in Section S 3. Miscellaneous S	TR TR										
Property in Sec. S	T R										
4. Lot No, Recorded 5. Private Claims	Plat		. l	A B (	C D	E F G	<b>→</b> H 1	JK	L M		
	•		2 3	-6	5	4	3	2	11		
do hereby certify that under requirem	ents of P.A. 74, Michigan I	survey on <u>July 21, 2000</u> P.A. of 1970, the corner points mentioned	. 4	7	8	9	10	11	12		
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5				18	17	16	15	14	13		
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			5 7 a 8 5 9	19	-20	21	22	23	24		
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			10 11	30	29	28	27	26	25		
			12	- 31	32	33	- 34	35	36		
		otes, West corrected between sect in post 20 links (13.20 feet)	13 ions 25	and 36	<u> </u>						
2. December 23,1991, Duane Found plow point 7 fee		C Liber 003 Page 025 of Deaner Road at approximately P.	I. of cent	terline (	of curve	,					
W. oak 18" W. pine 6"	North N06°E	217.21 feet 214.86 feet									
Tw. Cherry 20		214.32 feet									
Searched the apparent loc below surface of road with	ation of the original c wood along edge of pl	applied in restoring or reestablishing corner, excavated 2.00 feet x 2.00 low point in original soil. No othe	feet x 1 r eviden	ce fou	nd		und pl	low po	oint 4"		
C. Description of monument for Set remonumentation pipe	corner and accessories in place of plow point.	established to perpetuate locating the Set plow point and wood eviden 217.64 feet	ce next	es mor	HE LEGIS	r PCREM	COUNT	Y SUR	EY PEE		
Fnd nail E/S pine 10"	N16°E	215.27 feet	GROUP A	03 INC	ULLI	AL			4		
Set remon witness pipe/cars Set remon witness pipe/cars		31.16 feet 22.45 feet	, 0000			V	ĴŒ	$\overline{\mathcal{I}}$	, , , ,		
r		petuation of the position of the or	ninal co	rner		William 1	ingley, F	S, Chair	man		
•	tandard remonumenta	ation pipe consists of a Berntsen s	•		<b>2 3/8"</b> :	x 30" p	ipe wi	th a br	ass:		
Signed by \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	- burg	Date [5]	26	( or	<b>&gt;</b>						
Surveyor's Michigan License No. 30104 } Form approved by michigan state board of Land surveyors, Jan. 28, 1971 REVISED MAY 14, 1915 REVISED MAY 14, 1915											
					ADAPT	ED FOR W	ORD PROC	ESSING MA			

PAGE 318

LIBER 4