SURVEY & (REMONUMENTATION

JAN 31 2001

LIBER 3121 PAGE 650

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corner SECTION

STATE OF MICHIGAN COUNTY OF MUSAEGON RECEIVED FOR RECORD

2m nfc 2n

mber

	• ***							read Di	LU Z	O I	11	: 48
	Muskegon (County)	Located In	ì:	Corner	Code #			Mar	64	2	. 1.	09
1. Public I	and Survey	T <u>9N</u> R T R T R		<u>E-11</u>	***************************************		•	REGIS	TER	7aa OF (oseo Deeo	S .
in Sect 3. Miscell		S T R S T R S T R					Regis	ster of I)eeds	Star	mp &	File Nu
4. Lot No.	, Reco	ded Plat		· · · · · · · · · · · · · · · · · · ·			<u>а</u> в	C D	E F	<u> </u>	н :	[J]
5. Private	Claims					2			4	+	- 3	 2
hat under rand 2 abovenanual of Managemer above of a below:	A Vallier , in a sequirements of P.A. sequirements of P.A. se were in conformer or by a decree of a se were in conforman. Court of Law; estables of the more than 2 comern this certificate.	74, Michigan P.A. or nee with regulations of the United States Court of Law and /oce with the rules of lished, re-established	f 1970, the and rules the s Department or that the co the Michigan i, monument	corner points perefore as rec at of the inter priner points me a Board of Lar ed, recovered,	mentioned in lines quired in the curre ior, Bureau of La entioned in lines 3, d Surveyors or by found as express	1 5 nt 6 , 4 7	19-30-31-	20-29-32-32-	21	3	-10	
A. Descri	ption of original mo	nument and acces	sories and/	or subsequer	t restoration:							
1837 1881	John Mullett (G.L N 78° E N 47° E	20" Hemlock 8" Hemlock	20 Links 15 Links	inhad wa suje		F F	ECOR EVIEV Y MU	ON OF DED (VED & ISKEG(CORN RAT ON C	IER IFIE OUN	D VTY	4100 (L_
1891	County Survey Records show corner being established, no witnesses. PEER GROUP IN ACCORDANG WITH P.A. 345, OF 1990 County Survey records show a stone. No witnesses.										NCE	
1950's		Road Commission 15" Poplar 6" Hemlock			rner, but list no d	escriptio	n.					
1982		9" Cedar 20" Popt 6" Pine	nd" and plac									

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 4" x 30" cast-iron monument containing a "County Surveyors Cap" was found in a monument box on a fence line to the West. Witnesses verified with L.C.R.C. recorded in Liber 1246, Page 14. Position of the existing corner was accepted due to historical usage and documentation.

C,	Description of monument for corner and accessories established to perpetuate locating the position of the corner.

A 4" x 30" cast-iron monument containing a "County Surveyors" cap was found in a monument box.

 \mathbf{S} 39° Ε 55.56' 16" Cedar Found nail on SE side N 44° 63.63' 12" Pine Found nail on NW side E 65° W 50.091 Corner Fence Post Found 20D nail on N side 14° 155.19 Set 20D nail on N side

Signed by Date Surveyor's Michigan License No. FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1

REVISED MAY 14,1 REVISED JAN., 1 REVISED OCT., 1

STEPHEN VALLIER Land

Surveyor

No.

28428