ILAR CE 1899

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIVED FOR RECORD

For corners in

(County)	Located In:	Corner Code #
1. Public Land Survey	T <u>9N</u> R <u>14W</u> T R T R	I-3
<ol> <li>Property Controlling In Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S	
4. Lot No	, Recorded Plat	

1998 DEC 23 AM 8: 12

Carrie Carter REGISTER OF DEEDS


LIBER 2187 PAGE 905

Register of Deeds Stamp & File Number

I, Stephen V. Vallier , in a field survey on <u>December 11</u> , do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

established, re-established, monumented, recovered, found as expressed below:



Description of original monument and accessories and/or subsequent restoration:

1-3 1837

5. Private Claims \_

G.L.O. set post.

45° S W E

8.581

10" Beech

S 82°

17.16

14" Hemlock

1866-

Plat of Village of Ravenna surveyed by A. Egeiston.

1940 Era

County survey records page 12, iron bolt:

SE 43,43 18" Poplar NE 45.00' 18" Poplar NW 49.15 18" Maple

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990


M.C.R.C. tie book same as page 12 of Muskegon survey records. 1950 Era

## \*\*See Section A, page 2\*\*

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - Found ¾" x 12" iron pipe next to a 1" x 12" iron pipe, along side a 4" bolt, all above a pointed rock measuring 6" x 6" x 12". Accepted position of found corner due to the consistency in historical usage and documentation. Reset, over pointed rock, a 23/4" x 30" cast-iron monument with survey cap.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 23/2" x 30" cast-iron monument with county survey cap.

N 77° Ε 62.831 Telephone Pole Nail in east side S 64° W 52.73' Telephone Pole Nail in north side S 23° W 72.38 C/L Tele/Riser Ν 21° W 60.21 Power Pole Nail in west side S 40° Ε 41.93' **Utility Pole** Nail in southwest side N 28° 50.24 C/L Hydrant



Signed by Surveyor's Michigan License No.

Du 22, 1998

form approved by Michigan Statis Board of Professional Surveyors, Jan. 28, 1971

## Section "A"

1979	Corner	Corner recorded by John Nelson in Liber 1177, page 317, found 1" pipe.				
	Azi.	72°	51.42 '	Found nail north side of power pole.		
	Azi.	133°	35.26'	Found nail northeast side of power pole.		
	Azi.	244°	51.30'	Buried telephone cable riser box.		
	Azi.	337°	59.84	Found square spike northeast side of power pole.		
1979	9 Corner recorded by Francis Smith in Liber 1179, page 905, found 1" iron stake.					
	SW	72.80'		Spike in telephone pole.		
	SE	35.20'		Spike in guy pole.		
1	NE	51.40'		Spike in telephone pole.		
1985 D. Schiele recorded survey in Liber 1549, page 960, found steel bar.						
	NE	51.62'		Telephone pole		
	SE	35.22		Light pole		
	SW	72.75		Telephone pole		
	WNN	59.84'		Power pole		

STEPHEN VALLIER
Land
Surveyor
No.
28428

Sylv VIIII Du 22,1998

OUTSIEV A REMODER ENTITION

MAR 0 9 199<mark>9</mark>

SECTION