SURVEY & REMONUMENTATION

LIBER 3124 PAGE 923

STATE OF MICHIGAN COUNTY OF MUSTEGEN RECEIVED FOR RECORD

JAN 3 1 2001

200 DEC 29 AM 11: 23

SECTION

4. Lot No.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mark J	77 7a	irchild
REGISTER	OF	DEFES

Muskegon	Located in:	Corner C	ode#	Ì
(County)		1 477	к-3	1
I. Public Land Survey	TI	14W _		
m	T T S T	?		
2. Property Controlling in Section	\$	R		
3. Miscellaneous Property in Sec.	s T	R		

Register of Deeds Stamp & File Number

5. Private Claims		
I, Ralph W Var requirements of P.A.	nRiper in a field survey on De 74, Michigan P.A. of 1970, the corner pulations and rules therefore as required in	ooints mentioned in lines 1 and 2 above were in the current manual of survey instructions of the

United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

, Recorded Plat

Ā	B ,	С	D	£	F	G	н	Į	J	K	Ļ	M
1	1	_	\neg	$\neg \Gamma$	7		_		ĺ		_	╛
2	6 1	-	<u> 5</u>	-	4 		د ا	\neg	.— <u>2</u>		T i	-
3		}		-+	}	1						
4		-	8	\dashv	غ غ أ		1	ا	1	1	13	2
5				+	-		-					_
6	i	8 —	1	7	1	6 !	1	5 	1	4	1. 	3
7		 					├─┐	-				
8	1	9	2	0 {	2	1	 _2	[2 I	2	⊻3 I	2.	4
9	<u> </u>	<u> </u>					├-		├─-	├─		
10) :]]0	2	و	2	28 1	-	½'7— \	┼;	2 	-2	5—-
1	·	-	-	-		+-	Τ.	<u> </u>	1	† <u> </u>		6
12	2	3 ¹ 1	3	2 	<u> </u>	33 	-	34— 	Τ) 	<u> </u>	
11	ـــاء	ــــــــــــــــــــــــــــــــــــــ	ـــــــــــــــــــــــــــــــــــــــ	<u> </u>	<u> </u>	٠						

A. Description of original monument and accessories and/or subsequent restoration:

1837 GLO Set Section Post = Blue Beech 8" S54°W 38L & Ironwood 6" N48°W 26L

1950's MCRC Witness Sheets & Current MCRC Witness Book shown nothing at this Corner

J C Bueche, LCRC in 1987 Found 1/2" Round Iron = Nail in SE side of Twin 6" Oak N35°W 38.30' : Nail in W side of 10" Dead Tree No E 9.00'; Nail in W side of 8" Oak S45 E 14.39'; Nail in W side of 8" Oak S 45° E 14.39': Nail in S side of 18" Oak N 40°E 36.58': Centerline of Power Line N&S is West 100': Nail in S side of Tri. 16" Oak N90°W 45.11': Fence North

R W VanRiper & S V Vallier have found & used this Corner Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Pipe & Old Fence Line North

Historical usage, documentation and evidence of corner location reviewed and ratified

by Muskegon County Peer Group 7/11/2000

REVIEWED & RATIFIED BY MUSKEGON POSITION OF SAID PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

OF MICHIO

RALPH W

VAN RIPER

ROFESSIONAL

SURVEYOR

1/11/00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Set 2 3/4" Cast Iron "County Survey" Monument

Found Nail in SW side of Twin 10" Maple N 50° W 38.201

Found Nail in W side of 10" Dead Oak N 03° E 8.98

Found Nail in Sly side of 22" Oak 36.46 N 41° E

Found Nail in W side of 12" Oak s 49° E 14.35

Set Nail in E side of 12" Oak 7.97

N 79° W 44.61' Set Nail in N side of Triple 20" Oak s 36° W

16946 POFESSION

Signed by Japh W. Van The Surveyor's Michigan License No.