

FEB 0 9 2000

HINER 2326 PAGE 785

Filing Requirement of Act 74, Mich. P.A. 1970

or corners	in	SECTION

5. Private Claims

NC

LAND CORNER RECORDATION CERTIFICATE

STATE ()F	Mic	Cille	SAN.	
COUNTY	0F	MU	SKE	GCN	
RECEIVED) F	0Ř	RE(CORD	١

1999	DEC	27	PH	12:	4	5
------	-----	----	----	-----	---	---


GISTER OF DEEDS

er of Deeds Stamp & File Number

				100
Muskegon (County)	Located in	:	Corner Code #	1999
1. Public Land Survey	T <u>9N</u> T T	R <u>14W</u> R R	<u>K-6</u>	RE
 Property Controlling In Section Miscellaneous Property in Sec. 	\$ T \$ T \$ T \$ T	R R R		Registe
4. Lot No	_, Recorded Plat			

in a field survey on December Stephen V. Vallier do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. (John Mullett) set the quarter section post. 1837

11 Links

6" Beech

N 34° W

10 Links

6" Ironwood

1950's M.C.R.C.'s witness tie book notes an iron with no witness.

MARK F. FAIRCHILD MUSKEGON COUNTY Register of Deeds

Recorded Copy!

C. F. Lewandowski found an empty monument box and set a 4" x 30" cast-iron monument. Recorded L.C.R.C. in Liber 1984

130	M, Pa	ge 600	5.	
Eas	st	~	66.201	12" Elm
N	50°	E	44.26'	4" Elm
N	25°	W	68.21'	10" Elm
S	85°	W	67.20'	Power Pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 234" cast-iron monument with a county surveyor's cap in a monument box on an old fence line to the east and a tree line to the west. Accepted the position of corner due to historical usage and documentation. Evidence is inconclusive that the corner is a correct and true perpetuation of the G.L.O. corner.

East 66.45'

12" Elm Stump

S 85° W

67.20

Power Pole

Found nail on west side

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED. EY MUSKEGON COUNTY. PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Found a 23/4" cast-iron monument with a county surveyor's cap in a monument box.

East

66.45' 67.201 12" Elm Stump Power Pole

Found nail on west side

N 40° E

S 85° W

118.00'

Telephone Pole Found nail on south side

2656.72' Distance to K-5

North South

2653.03' Distance to K-7

Surveyor's Michigan License No. _ 2842 0

Date 12/22/99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28,

STEPHEN

VALLIER

No.

28428

Land Surveyor

REVISED MAY 14,19 REVISED JAN., 19 REVISED OCT., 19