SURVEY & REMONUMENTATION

UBER 1810 PAGE 567

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIVED THE THOORD

APR 2 8 1995

For corners in

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

1991 DEC 29 M 10: 13

2 avia	Cirter
REGISTER	OF DEEDS -

	Muskegon	_ Located In:	Corner Code ##	
	(County)	•		
1.	Public Land Survey	T <u>9</u> R <u>15</u>	G-8	
		T R		
		T R		
		T R		
2.	Property Controlling	S T R		
	in Section	S T R		
3.	Miscellaneous	S T R		
	Property in Sec.	S T R		


Register of Deeds Stamp & File Number

A 1591

110porty (11000).		
4. Lot No, Recorded Plat		
5. Private Claims	- ABCDEFGHIJKE	_
5. Frivate Claims	- ,	
\cdot .	\$\frac{6}{6}\frac{1}{5}\frac{4}{4}\frac{3}{3}\frac{1}{2}\frac{2}{1}\frac{1}{1}	_
	3	
Stophon W Wallior	4 7 - B - J - 9 - J - 10 - 11 - 11 - 11	
Stephen V. Vallier July 19 94 ,	5	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned		
	6 - 18 - 17 - 16 - 15 - 14 - 1	3
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the		
current manual of survey instructions of the United States Department of the Interior, Bureau of Land	'\ 	-
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5	8 10 20 21 22 23 2	_
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a		•
Court of Law: established, re-established, monumented, re-monumented, recovered, found as	9	
	10 20 20 28 27 26 2	_
expressed below:	'V -30-1-29-1-28-1-27-1-26-1-2	5-

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1837 GLO set 1/4 corner.
 - 1950's M.C.R.C. tie map Iron Pipe.
 - Found 1/2" Iron Pipe. J. Campbell Liber 1188 Page 208 (rec. survey) 1979
 - 1980
 - M.C.R.C. Found 1/2" Iron Pipe/Reset 1/2" rerod in monument box. C.F. Lewandowski Liber 1297 Page 934 Found 1/2" rerod in monument box Reset with 2 3/4" x 30" cast iron monument with County Survey Cap.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 2 3/4" cast iron monument with County Survey Cap. Accepted position of corner due to historical usage and documentation.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - 2 3/4" cast iron monument with County Survey Cap.

85.79' 20" Cherry with nail N 30 deg E

N 30 deg E 85.79' S 50 deg E 46.34'

V. Pole with nail 3" Maple with nail 93.53' S 45 deg W



Signed by Just Mile	Date Du 27, 1994
Signed by	Date
Surveyor's Michigan License No. 28428	ENDM APPROVED BY MICHIGAN STATE ROARD OF LAND SURVEYORS, JAN. 28, 1