

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MUSKEGON (County) Located In: Corner Code ##

1. Public Land Survey T 9N R 15W H-11

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ **SURVEY & REMONUMENTATION**

in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ **NOV 28 2000**

*Carrie Carter*  
REGISTER OF DEEDS

1994 DEC 27 AM 11:41

STATE OF MICHIGAN  
COUNTY OF MUSKEGON  
REGISTERED FOR RECORD

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_ SECTION \_\_\_\_\_

5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, STEPHEN V. VALLIER, in a field survey on JULY, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

- A. Description of original monument and accessories and/or subsequent restoration:
- 1837 GLO SET 1/4 CORNER S 37° W 5 LINKS 6" HEMLOCK N 63° E 8 LINKS 24" BEECH
  - 1985 WESTSHORE ENG. LBR. 1317, PG. 426 FD. 3/4" IRON PIPE SSE 101.70' P. POLE WNW 109.45' M. FENCE POST
  - 1980 J. CAMPBELL, LBR. 1188, PG. 210 INCORRECTLY FILED SECTION 22? 1990 WESTSHORE ENG. LBR. 1550, PG. 120 SET 2 3/4" X 30" CAST IRON MON. WITH COUNTY SURVEY CAP-REPLACED FOUND IRON
  - 1983 D. SCHIELE LBR. 1262, PG. 353 FOUND IRON PIPE S 2° E 103.28' NAIL P. POLE ENE 159.85' 12" WALNUT N 70° W 109.60' M. FENCE POST SSE 101.46' P. POLE S 3° W 33.00' IRON ROD WSW 123.15' 8" COTTONWOOD S 79° W 123.15' 10" COTTONWOOD

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- FOUND CAST IRON MONUMENT N 81° E 160.00' 14" WALNUT
  - 2 3/4" X 30" WITH COUNTY SURVEY CAP-ACCEPTED CORNER DUE TO HISTORICAL USAGE & DOCUMENTATION
  - 1990 WESTSHORE LBR. 1550, PG. 120 SET 2 3/4" X 30" CAST IRON MON. WITH COUNTY SURVEY CAP-REPLACED FOUND IRON
  - S 2° E 103.28' NAIL P. POLE
  - N 70° W 109.60' M. FENCE POST
  - S 3° W 33.00' IRON ROD
  - S 79° W 123.15' 10" COTTONWOOD
  - N 81° E 160.00' 14" WALNUT

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PLER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

*July 5, 1994*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

FOUND CAST IRON MONUMENT 2 3/4" X 30" WITH COUNTY SURVEY CAP

- S 2° E 103.28' NAIL P. POLE
- N 70° W 109.60' M. FENCE POST
- S 3° W 33.00' IRON ROD
- S 79° W 123.15' 10" COTTONWOOD
- N 81° E 160.00' 14" WALNUT

Signed by \_\_\_\_\_ Date July 27, 1994

Surveyor's Michigan License No. 28428

