

SURVEY &  
REMONUMENTATION

LIBER 1810 PAGE 28

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMISSION

MUSKEGON  
(County)

Located In:

Corner Code #

- |                                    |   |    |   |     |      |
|------------------------------------|---|----|---|-----|------|
| 1. Public Land Survey              | T | 9N | R | 15W | I-13 |
|                                    | T |    | R |     |      |
|                                    | T |    | R |     |      |
|                                    | T |    | R |     |      |
| 2. Property Controlling in Section | S |    | T | R   |      |
|                                    | S |    | T | R   |      |
| 3. Miscellaneous Property in Sec.  | S |    | T | R   |      |
|                                    | S |    | T | R   |      |

A1535

STATE OF MICHIGAN  
COUNTY OF MUSKEGON  
RECEIVED FOR RECORD  
1994 DEC 27 AM 11:41  
Doris Corbett  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, STEPHEN V. VALLIER in a field survey on JULY 11, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1837 GLD SET 1/4 CORNER

N 82 DEG. W 31 LINKS 6" HEMLOCK  
N 30 DEG. W 40 LINKS 7" HEMLOCK

1983 D. SCHIELE LBR. 1262 PG. 358  
FOUND CAST IRON MONUMENT IN BOX

1950'S M.C.R.C.

NE 82.10' P. POLE  
SE 98.0' 12" MAPLE  
SW 33.10' 8" MAPLE

NE 57.39' G. POLE  
SE 49.92' T. POLE  
SW 51.28' P. POLE  
NE 57.92' P. POLE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND CAST IRON MONUMENT WITH COUNTY SURVEY CAP (OTTAWA CORNER A-1) IN MON BOX.  
ACCEPTED POSITION OF CORNER BY HISTORICAL USAGE AND DOCUMENTATION:

1983 D. SCHIELE  
LIBER 1262 PAGE 358

NE 57.39' G. POLE  
SE 49.92' T. POLE  
SW 51.28' P. POLE  
NE 57.92' P. POLE

June 7, 1994  
POSITION OF CORNER  
RECORDED UNDER  
LIBER 1262 PAGE 358  
BY D. SCHIELE  
REGISTER OF DEEDS  
MICHIGAN  
JULY 17, 1994  
WITH A. J. B. OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

FOUND CAST IRON MONUMENT WITH COUNTY SURVEY CAP IN MONUMENT BOX.

N 54 DEG. W	111.40'	NAIL S SIDE P. POLE
S 58 DEG. W	79.78'	NAIL S SIDE 16" RED PINE
S 50 DEG. W	48.19'	NAIL N SIDE 14" RED PINE
S 15 DEG. W	32.83'	NAIL W SIDE 16" RED PINE
S 22 DEG. E	39.14'	NAIL W SIDE 12" APPLE
S 60 DEG. E	84.36'	NAIL N SIDE 14" APPLE

Signed by

*Stephen Vallier*

Date

*Dec 27 1994*

Surveyor's Michigan License No.

28428  
No. 28428

