

**SURVEY &
REMONUMENTATION**

APR 28 1995

LIBER 1810 PAGE 555

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF MUSKEGON
RECEIVED FOR RECORD
1994 DEC 29 AM 10:11
Doris L. Carter
REGISTER OF DEEDS

For corners in

MUSKEGON (County) Located In: Corner Code #:

1. Public Land Survey T 9 R 15 M-12

2. Property Controlling in Section S T R

3. Miscellaneous Property in Sec. S T R

A 1579

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

STEPHEN V. VALLIER, in a field survey on DECEMBER, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1837 GLO SET QUARTER CORNER
- 1950'S MUSKEGON COUNTY ROAD COMMISSION TIE MAP FOUND STONE
- 1982 C.F. LEWANDOWSKI LBR. 1242 PG. 320 FOUND LARGE STONE - RESET WITH 4" X 30" CAST IRON MONUMENT WITH COUNTY SURVEY CAP

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 4" CAST IRON MONUMENT WITH COUNTY SURVEY CAP

ACCEPTED POSITION AS BEST HISTORICAL DOCUMENTATION CONSISTANT WITH HISTORICAL USE

POSITION OF SAID
RECORDED CORNER
REVIEWED & RATIFIED
BY MUSKEGON COUNTY
PEER GROUP IN ACCORDANCE
WITH P.A. 345, OF 1990

Nov 8, 1994 su

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4" CAST IRON MONUMENT WITH COUNTY SURVEY CAP

- S 7° EAST 108.92' TO 6" ELM
- E 86.90' TO IRON POLE
- N 2665.40' DISTANCE TO NORTHEAST CORNER SECTION 36



Signed by Stephen Vallier

Date Nov 8, 1994

Surveyor's Michigan License No. 28428