FOR CORNERS OF -:	'LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY_8		D-3	
2. PROPERTY CONTROLL- ING IN SECTION——	N. S., R W.		
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO, REC	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
19,	in lines 1 and 2 above (ident  19.74, established, and in conformance with regula	rified with circles on index, re-established, monuments ations and rules therefore a he Interior, Bureau of Landentioned in lines 3,4 and 5 stablished or re-established	code diagram - over) were, i ed, re-monumented, recovered s required in the current man Management or by a decree o above were, in a field survey as expressed below and in c
A. Description of original mo	nument and accessories and/	or subsequent restoration:	
	•		
B. Description of corner evid	ence found and/or method ann	alied in restoring or re-estab	dishing corner:
Old Witnesses		<b>,</b>	
E N E, 113.75',SE Co	or. House		
SW, 70.1',14" Oak			
SE, 56.25', 8" Oak			
C. Description of monument	for corner and accessories es	stablished to perpetuate loc	ating the position of the com
found 3/4 pipe inter	rsection Wood St. & Gil	les Rd.	
S43° E, 38.53', tele	ephone pole, pk & tag.		
N22* W 34 15! Power	r pole, Pk & tag.		
Mar na 34.13. at onc.			
\$30° W, 70.15', 15"	Oak, Pk & Tag		
•	Oak, Pk & Tag		
•		DATE	
S30° W, 70.15', 15"			(SEAL)
\$30° W, 70.15', 15"  SIGNED BY	GISTRATION NO.		
S30° W, 70.15', 15"  SIGNED BY  SURVEYOR'S MICHIGAN RE	GISTRATION NO		