LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY 8	T. 10 N. R. 16 W	X D-4	
2. PROPERTY CONTROLL- ING IN SECTION———			
3. MISCELLANEOUS PROPERTY IN SECTION	_ ,T S., R E	<u> </u>	
4. LOT NO, RECO	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
			FILING NUMBER
the corner points mentioned i field survey on <u>January</u> restored as expressed below a of survey instructions of the U court of law. Furthermore	n lines 1 and 2 above (id 3 19 74, establish and in conformance with re United States Department of that the corner points	dentified with circles on index ned, re-established, monumente egulations and rules therefore a of the Interior, Bureau of Land mentioned in lines 3,4 and 5 the established or re-established	P.A. 74, Michigan P.A. of 1970, code diagram - over) were, in a ed, re-monumented, recovered or sequired in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contrs or, by a Decree of a Court of
A. Description of original mor	nument and accessories ar	nd/or subsequent restoration:	
		· ·	
B. Description of corner evidence Old Witnesses	ence found and/or method	applied in restoring or re-estab	olishing corner:
E, 65.75', 5" Sasafr	as		
WNW, 83.5', Power Po	ole		
S88.65', Power Pole			
C. Description of monument	for corner and accessorie	es established to perpetuate loc	ating the position of the corner:
2" Pipe 3' above gro	ound (tipped)		
@ end of Wood St., b	oottom hill		
N71° W, 83.3', Power	r Pole, Pk & tag		
N37°E, 76.5', SW cor	r. metal bldg.		
S7°E, 88.5', Transfe	ormer pole, Pk & tag	g ,	
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN RE			(SEAL)
FOR STATE AND UNITED S			
		DATE	N
APPROVED AND SIGNED BY	007	Bisel DATE	January 17, 1974
APPROVED AND SIGNED BY	MICHIGAN REGISTERE	E LAND SURVEYOR	(SEAL)
		18655	**************************************
SURVEYOR'S MICHIGAN RE	GISTRATION NO		

PAGE 2