LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	OCATED IN -:	CORNER CODE MUNISER	<i>,</i>
1. PUBLIC LAND SURVEY T.	N. F.		Nº 11
	9 N. //		
2. PROPERTY CONTROLL-3/,T. 3. MISCELLANEOUS PROPERTY IN SECTION 3/,T.	1	44-3	112
4. LOT NO, RECORDE			
4. LOI NO, RECORDE		<u> </u>	
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 1920, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1920, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
	.*		
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 34 IRON Pipe Reforence from Information			
17 121001 1 100	fornis h	on/ a 5000	ies whole
	ky m	.m. 18uck 19	5 V
C. Description of monument for co 3/4 I Ron Pipe N. 0-30 W. 10" S. 23° W. 3' S. 89° E. 12"			ating the position of the comer:
: :			
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN REGIST			(SEAL)
FOR STATE AND UNITED STATES AGENCIES:			
SIGNED BY	ILEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY		DATE	- .
	MICHIGAN REGISTERED LAN	D BURVETOR	(SEAL)