

APR 0 3 1998

LIBER 2052 PAGE 626

~~	A 2571	<i>P</i> 3 3 3 3	ı
	CTI	1 337	è
		C 11 A	a

Surveyor's Michigan License No. 28428

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MUSKEGON

RECEIVED	F03	RECORD

Mus	kegon	Local	ted In:	Corner Code	#	1997	DEC 30	PH 3	: 24	
	(County)			0001 0000	,			• •		
1 D	alia Land Cuminu	₊ 9	N A6W	G-9		\mathcal{A}_{α}	bbie. C	Onto	agina .	
1. Put	olic Land Survey		R				REGISTER OF			
	•						neg.strn of	DEEDS)	
			R R							
O Dro	nady Controlling									
	perty Controlling		R							
	Section		R		1	•				•
	cellaneous		R			Register of	Deeds Star	mp & F	ile Nu	nb
Pro	perty in Sec.	3	R							_
ا ا	Na	, Recorded Plat _	,							
4. LUI	nto Claima	, Recorded Flat _				<u>A B</u>	CDE	F G	н і .	1
J. FIIV	ate Claims			· · · · · · · · · · · · · · · · · · ·		2 6	5] 2_
						a			<u>Ī</u>	<u> </u>
						4				Ĺ
Stephe	en V. Vallier P.S.	, in a field surve	Novemb	er 4,	. 19 . 19	5			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	ov certify that unde	requirements of P.A.	74. Michigan P.A. o	of 1970, the corner po	,	ed	1-1-1		 - - 	T
		re in conformance wi					<u> </u>	16	15	4
	•	structions of the Uni				1 1	-{{-}-	┼-┼-	 	┢
		e of a Court of Law and with the rules of the					20	21	222	23—
		d, re-established, m						- W	-	Ł
	ed below:	o, 10 oblasmonos, m				[*] 1030_	;	28	272	 6
NOTE:	Not more than	4 corners, all in the	e same town and	d range, may be r	ecorded	11			┷╁-	L
	on this certifica					12 31-			343	_
						13		Ĭ		Ĭ
A. Des	scription of origin	al monument and	accessories and	or subsequent re	storation:					
	_									
1837	G.L.O. Set Po	st J. Mullett							•	
	South 36°		3 Links		10 Inch	Hemlock				
	North 79°		3 Links		10 Inch	Elm				
1981		· 1013, Page 593 -	D. Sandel		Found I	ron in Monume	nt Box			
1983		1263, Page 298 -		/ski						
		By 30 Inch Cast Ir								
	South 45°	East 4	1.75 Feet		Light Po	ole				
	South 55°	West 5	4.44 Feet		Power F	Pole				
	North 40°	West 6	7.97 Feet		Power F	Pole				
B. Des	cription of corne	r evidence found a	ind/or method ar	oplied in restoring	or reestabl	lishing corner:				
		By 30 Inch Cast Iro								
So		Undetermined, H		al Usage and Kn		nentation Verify	Position o	t Corr	ег.	
	North 38°		7.98 Feet		Pole	,				
	South 73°	East 4	1.75 Feet		Light Po	oie				
						THE RESERVE OF THE PARTY OF THE	CONTRACTOR OF THE PARTY OF THE	-	C STATES AND A	
					64	POSITION (OF SAID			ĺ
		•			1/4/97	RECORDED	COMMEN	- 17		
				ì	14/97	REVIEWED	& KATER	IU NITV		in and
				,	17.17	BY MUSKE	CON COO	TRIT VADOM	NCE	1
						PEER GRO	AN IN MOU	1000	.,,,,,	
						WITH P.A.	345, Ur		AND DESCRIPTION OF THE PERSON NAMED IN	-
						the material of the section of	•			
					-4	tina tha masitia	- of the oo			
C. Des	cription of monu	ment for corner and	d accessories es	stablished to perp	etuate loca	ting the position	i or the cor	mer:		
		Cast Iron Monume		Surveyor Cap Pla						
South	37° East 41.	75 Feet	Light Pole		Found N					
		98 Feet	Power Pole		Found N		_			
		76 Feet	Concrete C	Curb	Set Iron	Road at North	east Corne	ər		
		29 Feet	Stop Sign							
South	43° East 70.	00 Feet	20 Inch Ma	Ble cass	Set Nail					
				THE LO						

OF MICH รายคนยที่ VALLIER

Land Surveyer

No.

28428

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Date_

December 15, 1997