SURVEY & REMONUMENTATION

APR 0 3 1998

LIBER 2052 PAGE 576

STATE OF MICHIGAN COUNTY OF MUSKEGON RECEIVED FOR

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1997 DEC 30 PM 3: 0:	1997	DEC	30	Pil	3:	0
----------------------	------	-----	----	-----	----	---

For corners in		•	<u> </u>
Muskegon (County)	Located In:	Corner Code =##	CONTRACTOR OF THE PROPERTY OF
Public Land Survey	T <u>9N</u> R <u>17W</u>	L 1	
•	T R T R		
2. Property Controlling in Section	S T R S T R		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No 5. Private Claims	, Recorded Plat		A B C D E F G H I J K L

I, Ralph W VanRiper, in a field survey on July 29, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

North 1/4 Corner of Section 1, T9N, R117W

Post set by GLO Surveyors in 1837; W Oak 8" N 82° E 11L and W Oak North 15L

MCRC, 1950's Witness Map and Current Witness Book show nothing at this corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" Rod in Monument Box

Have records of M M Buck, F F Smith and C F Lewandoski using this corner. Accepted corner based on historical usage and documentation.



POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUCKELON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Set 2 3/4" Cast Iron Monument with County Survey Cap in Monument Box

N 69° E 89.581 Found Spike in S Side of Power Pole S 74° E 89.801 Set PK Nail in N Side of Power Pole 26.10 Found Spike in W Side of Power Pole South s 34° W 78.02 Set Spike in W side of 24" Oak N 59° W Set "+" in S Bolt of Light Pole Base 88.641 N 32° W 29.641 Found PK Nail in E Side of Service Pole WEST 15.65' Found 5/8" Rod in Monument Box, South 1/4 Corner of Section 36 TION R17W (L 13)



Signed by Mull-	Un Ta	Date Dec.	26,	1997	
Surveyor's Michigan License No.	16946				