## SHIPVEY & REMONUMENTATION

APR 0 3 1998

LIRED 2052 PAGE 583

COMMEN Coss

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIVED FOR RECORD

197 DEC 30 PM 3: 10

## SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

or corners in	•		April 1 to the
Muskegon	Located In:	Corner Code ##_	1 Carrie Carter
(County)	also (10 N 16 W)	(A-12) V	REDISTER OF DEEDS
Public Land Survey	T 10N R 17W	M 12	
	T R		
	T R		
	T R		
Property Controlling	S T R		
in Section	S T R		
Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S	<u></u>	
Lot No	Conorded Plat		
			A B C D E F G H I J K L
Private Claims			2 6 5 4 3 2

Ralph W VanRiper , in a field survey on . July 23 o hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned I lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land tanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a yourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below:

IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

v. Description of original monument and accessories and/or subsequent restoration:

1/4 Corner common to Sections 36 TION RI6W and 31 TION RI6W Post set by GLO Surveyors in 1837; Pine 18" S15°W 22L and Beech 6" N39°W 23L

MCRC, 1950's Witness Map: NE 91.52 SW Cor. of House; SW 47.57' 18" Cal.; NW 59.42 SE Cor. of House

MCRC, Current Witness Book does not include this area.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recorded Survey by J G Campbell; L 1126, P 732
Found 1/2 Pipe; Guy Pole S50°W 39.30 and Power Pole N45°E 34.99'

Found 3/4" Rod in Monument Box Accepted corner based on historical usage and documentation




Date

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4 Cast Iron Monument in Monument Box with County Survey Cap

N 36° E S 52° E 57.41 Set PK Nail in NW side of Power Pole 93.71 NW Corner of Brick Building (Jiffy Lube) S 32° E 65.43 Set PK Nail in SW side of Power Pole S 39° W 59.84' Set "+" in Concrete base of Light Pole S 79° W 100.57' Set PK Nail in N side of Utility Pole N 53° W 123.56' SE Corner of Building (Pop A Top)



Signed by _	Tall	4%	1/n	Th:
1	lichigan License		16946	

Dec. 26,1997