SURVEY: EMONUMENTATION

MAR 06 1998

LIBER 2050 PAGE 789

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ESK 239	¥2
STATE OF Middle, COUNTY OF MUSIC RECOVERS	

1997 DEC 22 PH 3: 06

Carrie Carrier

For corners in Muskegen County N

1. Public Land Survey

1 ocated in:

R R Comer Code #

G-7 T <u>10N</u> R <u>17W</u> R


2. Property Controlling S in Section

3. Miscellaneous Property in Sec.

Recorded Plat 4. Lot No 5. Private Claims

i, <u>Donald G. Sandel</u>, in a field survey on <u>July 7, 1997</u> hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



Register of Deeds Stamp & File Number

POSITION OF SAID REPORTED A RAPPIED LINUN COUNTY HE I GROUP IN ACCORDANCE V.IIII P.A. 346, OF 1990

A. Description of original monument and accessories and/or subsequent restoration:

(1) GLO: Set post corner sections 15, 16, 21 & 22, May 31, 1837

(2) LCRC: Liber 1126, Page 530 C.F.Lewandowski #7867, October 13, 1977, found 1" pipe:

Power Pole W Power Pole

29.30 30.32

S43°W, N22°W,

8" Maple 14" Maple 56.91 108.5

(3) Certificate of survey, D. Sandel #25870, July 25, 1990, found 1" pipe:

S43°W

8" Maple

56.91

N22°W w

14" Maple

Power Pole

108.5

Power Pole 29,30% B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1) Found 1" pipe 18" long over 1" pipe 12" long at center line of Weber Road, 122' North of center line of Memorial Drive. Verified corner location using existing witnesses.

(2) Historical usage, documentation, and evidence of corner location reviewed and ratified by the Muskegon County Peer Group, June 17, 1997.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set 3" D X 31" Cast Iron "County Survey" monument in place of found 1" pipe; witnessed as follows:

S89°E, set nail S side, Utility Pole, 29.17°

S12°E, set nail NE side, Utility Pole, 91.65'

S10°W, found E side of E post, Stop Sign, 172.65'

S68°W, set nail NW side, 12" Ash, 53.82'

N86°W, found nail N side, Utility Pole, 30.35° N20°W, set nail NE side, 18" Maple, 109.10'

OF MICHIGAN DONALD G SANDEL No. 25870 A OFESSION TO

25870

Date

December 1997