

MAR 0 6 1998

For corners in

4. Lot No.

5. Private Claims \_

## LIRED 2052 PAGE 571

## STATE OF MICHIGAN COUNTY OF NUSKECON RECEIVED FOR CLOCK

## SECTION LAND CORNER RECORDATION CERTIFICATE SECTION Filing Requirement of Act 74, Mich. P.A. 1970

1997 DEC 30 PM 3: 09

Muskegon (County)			Locate	ed In:	Corner Code ##	
4.	Public Land Survey	-	т <u>10</u>	N R 17W	G 12	
			Т	R	-	
			T	R		
			T	R		
2.	Property Controlling	S	T	R		
	in Section	S	T	R		
3:	Miscellaneous	S	Ţ	R		
	Property in Sec.	s	— т <sup>—</sup>			

\_ , Recorded Plat .

Carrie Carter
RESISTER OF DEEDS

Register of Deeds Stamp & File Number

, Ralph W VanRiper, in a field survey on	0ct. 30	97						
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the								
current manual of survey instructions of the United States Dep Management or by a decree of a Court of Law and/or that the co	partment of the Interio	r, Bureau of Land						

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Quarter Corner between Sections 33 and 34, T10N R17W

Post set by GLO Surveyors in 1837: Blk Oak 8" S57°W 23L and Blk Oak 7" N86°E 14L

MCRC, 1950's Witness Map and Current Witness Book does not included this area.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Rod

Have record that E H Peck; M M Buck and F F Smith used this corner

Accepted corner based on historical usage and documentation


(3)97

POSITION OF SAID
RECORDED COLMER
REVIEWED & TATMED
BY MUSKEGOL COUNTY
PEER GROUP IN ACCORDANCE
WITH P.A. 345, OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" Cast Iron Monument with County Survey Cap

N 20° E 11.49' Found Spike in E Side of 6" Oak S 80° E 10.89' Found Spike in S Side of 14" Oak S 25° E 16.19 Found Spike in S Side of 18" Oak S 34° W 30.23' Found Spike in NW Side of 18" Oak 35.50 West Found Spike in N Side of Twin 8" Oak N 19° W 26.80 Found Spike in SW Side of 18" Oak



·		.440444.	
Signed by Rall Willia 12.	Date	Dec. 26, 1997	•
Surveyor's Michigan License No. 16946		FORM APPROVED BY MICHIGAN STATE ROARD OF LAND SHRI	FYORS IAN 28 1971

A1892

REVISED MAY 14, 1975 REVISED JAN., 1983