

1888

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

*Carrie Carter*  
REGISTER OF DEEDS

STATE OF MICHIGAN  
COUNTY OF MUSKEGON  
RECEIVED FOR RECORD  
1993 DEC 29 PM 3:08

For corners in

Muskegon  
(County)

Located In:

Corner Code //

1. Public Land Survey	T <u>11</u> N	R <u>16</u> W	H 10
	T _____	R _____	_____
	T _____	R _____	_____
	T _____	R _____	_____
2. Property Controlling in Section	S _____	T _____	R _____
	S _____	T _____	R _____
3. Miscellaneous Property in Sec.	S _____	T _____	R _____
	S _____	T _____	R _____

Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

I, Ralph W. VanRiper, in a field survey on June 4, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

Center of Section 27, T 11 N, R 16 W, Dalton Township  
Not set by CLO Surveyors

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" Pinched Pipe as per Muskegon County Road Commission Witness Book	NE 23.85'	16" Oak
	SE 31.60'	16" Cherry
	SW 73.90'	20" Pine
	E 54.85'	12" Oak

Historical usage, documentation and evidence of corner location reviewed and ratified by Muskegon County Peer Group, June 1, 1993

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 4" by 20" Cast Iron Monument with County Survey Cap

N 50° E	23.90'	Fd. Spike in 20" Oak
S 78° E	62.47'	Set Spike in Quad. 10" Maple
S 40° E	31.64'	Fd. Spike in 16" Cherry
S 02° W	22.60'	Set Spike in 16" Oak
N 82° W	17.33'	Set Spike in 12" Oak
N 17° W	10.63'	Set Spike in 12" Oak



Signed by *Ralph W. Van Riper* Date Dec. 28, 1993  
 Surveyor's Michigan License No. 16946