

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Marquette COUNTY  
43  
T 42 R 24 W

DESCRIPTION OF CORNER Section corner for sections 31/32 T43N R24W  
6/5 T42N R24W

CORNER MONUMENT 1" iron pipe

DATE MONUMENT PLACED AND WITNESSED 9/8/69, F. J. Bray

WITNESSES TO CORNER..... 8" Aspen (S.31) (NBT) N 40° W, 45½ links



8" Aspen (S.32) (NBT) N 24° E, 54 links

7" Aspen (S. 6) (NBT) S 14° W, 21 links

AND

12" Cedar stump (NBT) S 69° W, 42 links

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was rewitnessed as set by Marquette County Road Commission.  
Corner was set approximately 40 years ago.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 10/2/69  
REGISTERED LAND SURVEYOR  
Frank J. Bray

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68