

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Marquette COUNTY  
43  
T 42 N R 25 W

DESCRIPTION OF CORNER 1/4 corner for sections  $\frac{32}{5}$  T43N R25W  
T42N R25W

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/27/69, F. J. Bray with B. McDonald

WITNESSES TO CORNER..... 10" Cedar (1/4 S) (NBT) N 11° E, 14½ links



7" Tamarack (1/4 S) (NBT) S 72° W, 28½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from original cedar B.T. to NE with overgrowth of upper and lower faces. Scribe marks visible on overgrowth of upper face. Rotted tamarack stump in proper position to NW for other B.T.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE

9/25/69

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68