LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

į

For corners in		Filing Requirement of Act 74, Mich. P.		370
	Marquette	Located In:	Carpor Codo -++	
_	(County)	Located in:	Corner Code ≠≠	
	Public Land Survey	T R		
1.	Fublic Land Sulvey	T R		
		T R		
		T R		
2.	Property Controlling	s <u>5</u> T <u>42N</u> R <u>25W</u>	.14	
	in Section	S T R		
3.		S T R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		
A	Lot No	Recorded Plat		
				A B C D E F G H I J K L M
•				2 6 5 5 1 2 1 2 1 1
				3
	B 11 B 111.	•		4 - 7 - 8 - 9 - 10 - 11 - 12 - 12
l,		, in a field survey on		5
			of 1970, the corner points mentioned at rules therefore as required in the	6 18 17 16 15 14 13
cur	rent manual of survey insti	ructions of the United States Depar	tment of the Interior, Bureau of Land	7
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			8 19 20 21 22 23 24	
Court of Law; established, re-established, monumented, re-monumented, recovered, found as			9	
expressed below:			10 30 29 28 27 26 25	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			11	
	on this certificate	•		12 31 32 33 34 35 36
A.	Description of original	monument and accessories an	d/or subsequent restoration:	13
B. 14	·	ment in place with be	applied in restoring or reestablish aring trees cutstumps	-
				•
_				
C.	Description of monum	ent for corner and accessories	established to perpetuate locating	the position of the corner:
14	DNR Monument 4" balsam, N84 3" fronwood, N 7" maple, N57W 3" aspen, S36E	121W, 69.7' 1, 76.3'		

Signed by Cavil 13- Balbett Date 1-27-87

Surveyor's Michigan License No. RLS 21558

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983