

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 42.. NR. 26 W..

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 14, 15, 22, 23

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap

WITNESSES TO CORNER

<u>10" Cedar</u>	<u>N 67° E</u>	<u>32 links</u>
	<u>"S 14 NBT"</u>	
<u>8" Cedar</u>	<u>N 42° W</u>	<u>52 links</u>
	<u>"S 15 NBT"</u>	
<u>7" Hard Maple</u>	<u>S 52° E</u>	<u>21 links</u>
	<u>"S 23 NBT"</u>	

-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Y. Birch B.T. in place in poor condition.

Corner shown to us by Arne Metsa, District Forester.

Corner placed and witnessed 1/18/57.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2-7-57  
REGISTERED LAND SURVEYOR