

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43 ^N R 24W

DESCRIPTION OF CORNER 1/4 Corner for sections 6/5

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-18-72 F. J Bray

WITNESSES TO CORNER..... 8" Cedar (1/8) (NBT) N 80° E, 13.6'



10" Cedar (1/8) (NBT) S 49° W, 21.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from B.T. to S.E. (Tamarack stub with faces and scribe marks visible) B.T. to S.W. (Tamarack stump in rotted condition with overgrowth visible).

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE 11-17-72