

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Marquette COUNTY


T 43N R 24W

DESCRIPTION OF CORNER East 1/16 corner for sections  $\frac{6}{7}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 12-4-72 F. J. Bray

WITNESSES TO CORNER..... 4" Cedar (E 1/16) (BT) S69°W 2.6'



7" Cedar (E 1/16) (BT) N65°E .8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This section was mid=point and on a line between section corners east and  
 $\frac{1}{2}$ / $\frac{1}{4}$  corner west.

SURVEYOR'S SEAL

DISTRIBUTION:

Forestry Division, Lansing

SIGNED

Frank J. Bray  
REGISTERED LAND SURVEYOR

Frank J Bray

DATE 12-20-72